## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Details : VE959									
Priority:	High								
Created By:	Admin - Apurva Vajaria								
Complaint Mob. No. :	9833857590								
Technician Name	Atique Salmani			Tech :	echnician Mobile		8080922984		
Ticket Type :	Complain Date & Time :		e :	22-01-2020 01:41:42					
Vendor Details :									
Company Name/Client Name :	Kiran Tower CHS	r Customer's Mobile :		9833857590			Name :	Kalpesh Sir	
Address:									
Mumbai,,,, Maharashtra									
AMC Details :									
Expiry Date :	30-06-2020 12:00:00			Type:		Non-Comprehensive			
<b>Product Name:</b>	Intercom								
Complain:	2-3vflats issue								
Technician Comment :	most off falte phone issue need 8 phone and a502 need white phone 1402 B wing port issue.								
Complain Operator :	Desktop - Apurva Vajaria								
Remark:	most off falte phone issue need 8 phone and a502 need white phone 1402 B wing port issue.								
<b>Status History:</b>	Date Time	Technicia	Technician Name		atus		Remark		Sign
	22-01-2020 01:43:	53 Atique Sa	lmani	Completed		most off falte phone issue need 8 phone and a502 need white phone 1402 B wing port issue.		1/1/2	
	22-01-2020 01:41:53 Atique		lmani	New					-
	22-01-2020 01:41:	44 Atique Sa	lmani	New					-
Previous Complain History :	Date Time Technician N		cian Nam	ame		Remark			
	02-08-2023 05:11:	58 Kalpesh S	Kalpesh SubhashG				intercom issue solved Intercom line lat to Duct cable not found		
	26-07-2023 10:03:	17 Kalpesh S	Kalpesh SubhashGu		B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK				