

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1196																									
Priority :	High																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9220755431																								
Technician Name :	Mahindra Prajapati		Technician Mobile :	7678020599																					
Ticket Type :	Complain	Date & Time :	20-02-2020 05:20:09																						
Vendor Details :																									
Company Name/Client Name :	Dahisar Kaka	Customer's Mobile :	9220755431	Name :	Karan Soni																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Access																								
Complain :	lock not working																								
Technician Comment :	lock is amps changing on client side																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	lock is amps changing on client side																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>22-02-2020 12:18:43</td><td>MahindraPrajapati</td><td>Completed</td><td>lock is amps changing on client side</td><td></td></tr><tr><td>21-02-2020 10:54:56</td><td>MahindraPrajapati</td><td>New</td><td></td><td>-</td></tr><tr><td>20-02-2020 05:20:09</td><td>MahindraPrajapati</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	22-02-2020 12:18:43	MahindraPrajapati	Completed	lock is amps changing on client side		21-02-2020 10:54:56	MahindraPrajapati	New		-	20-02-2020 05:20:09	MahindraPrajapati	New		-
Date Time	Technician Name	Status	Remark	Sign																					
22-02-2020 12:18:43	MahindraPrajapati	Completed	lock is amps changing on client side																						
21-02-2020 10:54:56	MahindraPrajapati	New		-																					
20-02-2020 05:20:09	MahindraPrajapati	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>15-04-2023 10:52:41</td><td>SantoshPathak</td><td>Kalpesh visited - Extension number 235 - ok</td></tr><tr><td>09-03-2023 11:25:07</td><td>Atique Salmani</td><td>One smmps cahaned and working ok and which one cameras fractuating some light reflection and some i.r burn so cameras need to changed . also check restart dvr working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	15-04-2023 10:52:41	SantoshPathak	Kalpesh visited - Extension number 235 - ok	09-03-2023 11:25:07	Atique Salmani	One smmps cahaned and working ok and which one cameras fractuating some light reflection and some i.r burn so cameras need to changed . also check restart dvr working ok.											
Date Time	Technician Name	Remark																							
15-04-2023 10:52:41	SantoshPathak	Kalpesh visited - Extension number 235 - ok																							
09-03-2023 11:25:07	Atique Salmani	One smmps cahaned and working ok and which one cameras fractuating some light reflection and some i.r burn so cameras need to changed . also check restart dvr working ok.																							