




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE3417</b>																																			
<b>Priority :</b>	Low																																		
<b>Created By :</b>	Admin - Apurva Vajaria																																		
<b>Complaint Mob. No. :</b>	9220755431																																		
<b>Technician Name :</b>	Yogesh Desai		<b>Technician Mobile :</b>	8080922963																															
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	12-07-2021 12:12:38																																
<b>Vendor Details :</b>																																			
Company Name/Client Name :	Dahisar Kaka	Customer's Mobile :	9220755431	Name :	Karan Soni																														
<b>Address :</b>																																			
Mumbai , , , , Maharashtra																																			
<b>AMC Details :</b>																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
<b>Product Name :</b>	Ppm																																		
<b>Complain :</b>	Cctv ppm																																		
<b>Technician Comment :</b>	New biometric device installed . and four fingers also added in device. biometric is working ok and also opening on pressing finger on device																																		
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																																		
<b>Remark :</b>	New biometric device installed . and four fingers also added in device. biometric is working ok and also opening on pressing finger on device																																		
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>28-07-2021 07:42:00</td><td>YogeshDesai</td><td>Completed</td><td>New biometric device installed , and four fingers also added in device. biometric is working ok and also opening on pressing finger on device</td><td></td></tr><tr><td>28-07-2021 02:59:14</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>28-07-2021 02:57:20</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>12-07-2021 12:13:43</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>12-07-2021 12:12:38</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	28-07-2021 07:42:00	YogeshDesai	Completed	New biometric device installed , and four fingers also added in device. biometric is working ok and also opening on pressing finger on device		28-07-2021 02:59:14	YogeshDesai	New		-	28-07-2021 02:57:20	YogeshDesai	New		-	12-07-2021 12:13:43	YogeshDesai	New		-	12-07-2021 12:12:38	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																															
28-07-2021 07:42:00	YogeshDesai	Completed	New biometric device installed , and four fingers also added in device. biometric is working ok and also opening on pressing finger on device																																
28-07-2021 02:59:14	YogeshDesai	New		-																															
28-07-2021 02:57:20	YogeshDesai	New		-																															
12-07-2021 12:13:43	YogeshDesai	New		-																															
12-07-2021 12:12:38	YogeshDesai	New		-																															
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>29-05-2021 10:07:32</td><td>Neeraj Chauhan</td><td></td></tr><tr><td>15-04-2021 02:41:48</td><td>Atique Salmani</td><td>2 line intercom issue resolved one phone Faulty changed and second is ro zer box issue so direct this one and 2cameras shifting done one camera cable use 2 mtr.</td></tr></tbody></table>					Date Time	Technician Name	Remark	29-05-2021 10:07:32	Neeraj Chauhan		15-04-2021 02:41:48	Atique Salmani	2 line intercom issue resolved one phone Faulty changed and second is ro zer box issue so direct this one and 2cameras shifting done one camera cable use 2 mtr.																					
Date Time	Technician Name	Remark																																	
29-05-2021 10:07:32	Neeraj Chauhan																																		
15-04-2021 02:41:48	Atique Salmani	2 line intercom issue resolved one phone Faulty changed and second is ro zer box issue so direct this one and 2cameras shifting done one camera cable use 2 mtr.																																	