







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4587																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9220755431																																		
Technician Name :	Yogesh Desai		Technician Mobile :	8080922963																															
Ticket Type :	Complain	Date & Time :	15-01-2022 12:49:43																																
Vendor Details :																																			
Company Name/Client Name :	Dahisar Kaka	Customer's Mobile :	9220755431	Name :	Karan Soni																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	Fire																																		
Complain :	fire extinguisher need to hang																																		
Technician Comment :	four fire extinguisher installed as client request .																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	four fire extinguisher installed as client request .																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>17-01-2022 03:33:44</td><td>YogeshDesai</td><td>Completed</td><td>four fire extinguisher installed as client request .</td><td></td></tr><tr><td>17-01-2022 10:43:22</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>15-01-2022 01:48:15</td><td>YogeshDesai</td><td>Work Pending</td><td>Five fire extinguisher installed . Remaining four pending coz no L bracket with client.</td><td></td></tr><tr><td>15-01-2022 12:50:05</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>15-01-2022 12:49:43</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	17-01-2022 03:33:44	YogeshDesai	Completed	four fire extinguisher installed as client request .		17-01-2022 10:43:22	YogeshDesai	New		-	15-01-2022 01:48:15	YogeshDesai	Work Pending	Five fire extinguisher installed . Remaining four pending coz no L bracket with client.		15-01-2022 12:50:05	YogeshDesai	New		-	15-01-2022 12:49:43	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																															
17-01-2022 03:33:44	YogeshDesai	Completed	four fire extinguisher installed as client request .																																
17-01-2022 10:43:22	YogeshDesai	New		-																															
15-01-2022 01:48:15	YogeshDesai	Work Pending	Five fire extinguisher installed . Remaining four pending coz no L bracket with client.																																
15-01-2022 12:50:05	YogeshDesai	New		-																															
15-01-2022 12:49:43	YogeshDesai	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>10-02-2022 02:50:36</td><td>Siddhesh Chavan</td><td>ppm done and all camera working ok</td></tr><tr><td>24-01-2022 12:43:30</td><td>Atique Salmani</td><td>4 camera issue resolved by changed SMPS and also software issue resolved and changed dvr pachcode use 4 rj45 connector and all working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	10-02-2022 02:50:36	Siddhesh Chavan	ppm done and all camera working ok	24-01-2022 12:43:30	Atique Salmani	4 camera issue resolved by changed SMPS and also software issue resolved and changed dvr pachcode use 4 rj45 connector and all working ok.																					
Date Time	Technician Name	Remark																																	
10-02-2022 02:50:36	Siddhesh Chavan	ppm done and all camera working ok																																	
24-01-2022 12:43:30	Atique Salmani	4 camera issue resolved by changed SMPS and also software issue resolved and changed dvr pachcode use 4 rj45 connector and all working ok.																																	