## Vallabh Enterprises

**Regd. Office** : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 Support : | **W** : www.vallabhenterprises.com **E** : vallabhsecure@yahoo.co.in

Service Status Details : VE11090 **Priority** : Low **Created By :** Admin - Apurva Vajaria Complaint 9920898984 Mob. No. : Technician **Technician Mobile :** 8080922984 Atique Salmani Name : 11-03-2024 01:39:48 **Ticket Type :** AMC visiting **Date & Time : Vendor Details :** Velji P. And Customer's Mobile : 9920898984 Kaushik Sir Company Name : Name/Client Sons Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 15-08-2020 12:00:00 Comprehensive Expiry Date : Type : **Product Name :** Ppm CCTV / Access / Biometric PPM need to do **Complain**: Cctv chek all working ok Ashok sir cabin tv was off becz extender power loose sonused another **Technician Comment** : plug point and also Ashok sir cabin wire mash clear with tie-up and of biomatric tonarun sir explain how to generate individual report But some out door punching issue and confrence room lock enable but door is fricting need to down littil abit .and also kaushik sir required on /off swich in confrence room cabling need to do 5/to7 meters only. Complain Desktop - Apurva Vajaria **Operator** : **Remark** : Cctv chek all working ok Ashok sir cabin tv was off becz extender power loose sonused another plug point and also Ashok sir cabin wire mash clear with tie-up and of biomatric tonarun sir explain how to generate individual report But some out door punching issue and confrence room lock enable but door is fricting need to down littil abit .and also kaushik sir required on /off swich in confrence room cabling need to do 5/to7 meters only . **Status History :** Technician **Date Time** Status Remark Sign Name 11-03-2024 Atique Completed Cctv chek all working ok Ashok sir cabin 05:18:19 Salmani tv was off becz extender power loose sonused another plug point and also Ashok sir cabin wire mash clear with tieup and of biomatric tonarun sir explain how to generate individual report But some out door punching issue and confrence room lock enable but door is fricting need to down littil abit .and also kaushik sir required on /off swich in confrence room cabling need to do 5/to7 meters only 11-03-2024 Atique New 01:39:57 Salmani

Previous Complain History :	Date Time	Technician Name	Remark
	13-03-2024 02:16:55		
	08-02-2024 01:16:24	Siddhesh Chavan	sir cabin tv issue resoved and splitter adpter faylty repaced with new adpter issue resoved - old adaptor returned