Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E: valiabhsecure@yanoo.co.in							
Service Status Details : VE12238							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob.	9920898984						
Technician Name:	Atique Salmani		Technicia :	an Mobile 8080922984			
Ticket Type :	Complain	Date & Time :	25-07-202	24 12:13:22			
Vendor Details :							
Company Name/Client Name :	Velji P. And Sons	Customer's Mobile:	e 99208989	984	Name :	Kaushik Sir	
Address:							
Mumbai,,,, Maharashtra							
AMC Details:							
Expiry Date :	15-08-2020 12:00:00		Type:	Type: Compreher		/e	
Product Name:	CCTV						
Complain:	1)middle camera black and white issue 2)Pantry camera and waiting Area also black & white issue						
Technician Comment :	Camera nmbr 6 passsage + Xerox machin e issue need to changed Also camera nmbr 15 need to changed Camera nmbr 7 pantry issue resolve Camera nmbr 3 behind reception issue resolved color view working ok.						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	Camera nmbr 6 passsage + Xerox machin e issue need to changed Also camera nmbr 15 need to changed Camera nmbr 7 pantry issue resolve Camera nmbr 3 behind reception issue resolved color view working ok.						
Status History :	Date Time	Technician Name	Status		Remark	Sign	
	26-07-2024 12:16:10	Atique Salmani Atique Salmani	Awaiting Spares	Xerox machi changed Als need to char pantry issue nmbr 3 behi	or 6 passsage + in e issue need to o camera nmbr 15 nged Camera nmbr resolve Camera nd reception issue or view working ok		
	10:47:22						
Previous Complain	Date Time	Technician Nam	Technician Name		Remark		
History:	12-12-2024 10:40:12	2 Sonu Kumar	Cctv access	Cctv access ppm Dane all working ok all camera lens clean			
	27-09-2024 10:48:16	6 MayurYadav		Main door released by disconnect main door lock connector from device Note- main door device bottom screw missing			