

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1246																									
Priority :	High																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9920898984																								
Technician Name :	Zainul Shaikh		Technician Mobile :	8080922971																					
Ticket Type :	Complain	Date & Time :	28-02-2020 02:18:16																						
Vendor Details :																									
Company Name/Client Name :	Velji P. And Sons	Customer's Mobile :	9920898984	Name :	Kaushik Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	15-08-2020 12:00:00		Type :	Comprehensive																					
Product Name :	CCTV																								
Complain :	extender issue																								
Technician Comment :	hdmi extender power supply plug is loose from tv side soo now properly connected. working ok.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	hdmi extender power supply plug is loose from tv side soo now properly connected. working ok.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>29-02-2020 11:06:58</td><td>ZainulShaikh</td><td>Completed</td><td>hdmi extender power supply plug is loose from tv side soo now properly connected. working ok.</td><td></td></tr><tr><td>28-02-2020 06:34:40</td><td>ZainulShaikh</td><td>New</td><td></td><td>-</td></tr><tr><td>28-02-2020 02:18:16</td><td>ZainulShaikh</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	29-02-2020 11:06:58	ZainulShaikh	Completed	hdmi extender power supply plug is loose from tv side soo now properly connected. working ok.		28-02-2020 06:34:40	ZainulShaikh	New		-	28-02-2020 02:18:16	ZainulShaikh	New		-
Date Time	Technician Name	Status	Remark	Sign																					
29-02-2020 11:06:58	ZainulShaikh	Completed	hdmi extender power supply plug is loose from tv side soo now properly connected. working ok.																						
28-02-2020 06:34:40	ZainulShaikh	New		-																					
28-02-2020 02:18:16	ZainulShaikh	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>26-07-2023 10:55:25</td><td>Shiva Meena</td><td>Lite adpatr cheng and batan spark nuw not cheng and camera and Lite wark complete</td></tr><tr><td>30-06-2023 11:08:20</td><td>MayurYadav</td><td>Software reinstall in system</td></tr></tbody></table>					Date Time	Technician Name	Remark	26-07-2023 10:55:25	Shiva Meena	Lite adpatr cheng and batan spark nuw not cheng and camera and Lite wark complete	30-06-2023 11:08:20	MayurYadav	Software reinstall in system											
Date Time	Technician Name	Remark																							
26-07-2023 10:55:25	Shiva Meena	Lite adpatr cheng and batan spark nuw not cheng and camera and Lite wark complete																							
30-06-2023 11:08:20	MayurYadav	Software reinstall in system																							