## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE1331 **Priority** : High **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9920898984 **No. : Technician Name** Sachin Pawar **Technician Mobile** 8080922981 Complain Date & Time : 06-03-2020 06:44:08 **Ticket Type :** Vendor Details : Velji P. And Customer's Mobile 9920898984 Name : Kaushik Sir Company Name/Client Name Sons Address : Mumbai,,,, Maharashtra **AMC Details :** 15-08-2020 12:00:00 Comprehensive Expiry Date : Type : **Product Name :** Time And Attendance NEED SOME SPECIFIC REPORTS (KAUSHIK SIR) **Complain**: report is given to kaushik sir and auto backup settings at server end is also done. Technician **Comment**: Complain Desktop - Apurva Vajaria **Operator** : **Remark :** report is given to kaushik sir and auto backup settings at server end is also done. **Status History : Date Time Technician Name** Status Remark Sign 11-03-2020 01:33:47 SachinPawar Completed report is given to kaushik sir and auto backup settings at server end is also done. 11-03-2020 10:17:50 SachinPawar New 06-03-2020 06:44:08 SachinPawar New **Previous Technician Name Date Time** Remark **Complain History** 28-02-2020 02:18:16 ZainulShaikh hdmi extender power supply plug is loose from tv side soo now properly connected. working ok. 16-01-2020 03:26:21 SachinPawar 1.biometric machin logs got full so unable to punch now att logs get clear and backup for the same. 2 two cameras off bcoz of power supply faulty now change with self supply and its working.