

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2025																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9920898984																																		
Technician Name :	Mayur Yadav		Technician Mobile :	8411951301																															
Ticket Type :	Complain	Date & Time :	14-10-2020 11:34:00																																
Vendor Details :																																			
Company Name/Client Name :	Velji P. And Sons	Customer's Mobile :	9920898984	Name :	Kaushik Sir																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	15-08-2020 12:00:00		Type :	Comprehensive																															
Product Name :	Access																																		
Complain :	mobile software to install																																		
Technician Comment :	F22 network connectivity issue solve working ok Ethernet and wifi ip same. etime traklite configuration done																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	F22 network connectivity issue solve working ok Ethernet and wifi ip same. etime traklite configuration done																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>20-10-2020 03:05:42</td><td>MayurYadav</td><td>Completed</td><td>F22 network connectivity issue solve working ok Ethernet and wifi ip same. etime traklite configuration done</td><td></td></tr><tr><td>20-10-2020 12:18:42</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>20-10-2020 12:09:26</td><td>MayurYadav</td><td>Work Pending</td><td>mobile software setup done device connectivity issue</td><td></td></tr><tr><td>14-10-2020 11:34:19</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>14-10-2020 11:34:00</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	20-10-2020 03:05:42	MayurYadav	Completed	F22 network connectivity issue solve working ok Ethernet and wifi ip same. etime traklite configuration done		20-10-2020 12:18:42	MayurYadav	New		-	20-10-2020 12:09:26	MayurYadav	Work Pending	mobile software setup done device connectivity issue		14-10-2020 11:34:19	MayurYadav	New		-	14-10-2020 11:34:00	MayurYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																															
20-10-2020 03:05:42	MayurYadav	Completed	F22 network connectivity issue solve working ok Ethernet and wifi ip same. etime traklite configuration done																																
20-10-2020 12:18:42	MayurYadav	New		-																															
20-10-2020 12:09:26	MayurYadav	Work Pending	mobile software setup done device connectivity issue																																
14-10-2020 11:34:19	MayurYadav	New		-																															
14-10-2020 11:34:00	MayurYadav	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>02-12-2020 11:00:52</td><td>Ravi Rajbhar</td><td></td></tr><tr><td>21-11-2020 12:47:23</td><td>Siddhesh Chavan</td><td>door butan cable disconnect and after reconnect and working ok and door open</td></tr></tbody></table>					Date Time	Technician Name	Remark	02-12-2020 11:00:52	Ravi Rajbhar		21-11-2020 12:47:23	Siddhesh Chavan	door butan cable disconnect and after reconnect and working ok and door open																					
Date Time	Technician Name	Remark																																	
02-12-2020 11:00:52	Ravi Rajbhar																																		
21-11-2020 12:47:23	Siddhesh Chavan	door butan cable disconnect and after reconnect and working ok and door open																																	