




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE6530</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	8097384039																								
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	08-10-2022 10:49:36																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Ritambhara Vishva Vidyapeeth - College	Customer's Mobile :	8097384039	Name :	Kedar Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	31-05-2021 12:00:00		Type :	Comprehensive																					
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	1st floor exam room - 1 nos, 3rd floor classroom - 1 nos camera off issue																								
<b>Technician Comment :</b>	1 st floor exam room camera issue resolved and install new poe injector 3 floor 304 room camera poe injector install and camera issue resolved and working ok and 2 dc pin use																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	1 st floor exam room camera issue resolved and install new poe injector 3 floor 304 room camera poe injector install and camera issue resolved and working ok and 2 dc pin use																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-10-2022 12:37:46</td><td>Siddhesh Chavan</td><td>Completed</td><td>1 st floor exam room camera issue resolved and install new poe injector 3 floor 304 room camera poe injector install and camera issue resolved and working ok and 2 dc pin use</td><td></td></tr><tr><td>08-10-2022 10:50:11</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>08-10-2022 10:49:36</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-10-2022 12:37:46	Siddhesh Chavan	Completed	1 st floor exam room camera issue resolved and install new poe injector 3 floor 304 room camera poe injector install and camera issue resolved and working ok and 2 dc pin use		08-10-2022 10:50:11	Siddhesh Chavan	New		-	08-10-2022 10:49:36	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
08-10-2022 12:37:46	Siddhesh Chavan	Completed	1 st floor exam room camera issue resolved and install new poe injector 3 floor 304 room camera poe injector install and camera issue resolved and working ok and 2 dc pin use																						
08-10-2022 10:50:11	Siddhesh Chavan	New		-																					
08-10-2022 10:49:36	Siddhesh Chavan	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-10-2022 02:06:39</td><td>Ravi Rajbhar</td><td></td></tr><tr><td>20-09-2022 11:06:59</td><td>YogeshDesai</td><td>second floor camera changed new camera install. library camera issue solved by using poe injector for power camera now working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-10-2022 02:06:39	Ravi Rajbhar		20-09-2022 11:06:59	YogeshDesai	second floor camera changed new camera install. library camera issue solved by using poe injector for power camera now working ok											
Date Time	Technician Name	Remark																							
19-10-2022 02:06:39	Ravi Rajbhar																								
20-09-2022 11:06:59	YogeshDesai	second floor camera changed new camera install. library camera issue solved by using poe injector for power camera now working ok																							