## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

E: valiabnsecure@yanoo.co.in							
Service Status Det	aus: VE8061						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	8097384039						
Technician Name:	Ravi Rajbhar		Techn:	nician Mobile 8080922965			
Ticket Type :	Complain	Date & Time :	08-04	04-2023 10:27:07			
Vendor Details :							
Company Name/Client Name :	Ritambhara Vishva Vidyapeeth - College	Customer's Mol:	pile 80973	384039	Name:	Kedar Sir	
Address:							
Mumbai , , , , Mah	arashtra						
AMC Details :							
Expiry Date :	31-05-2021 12:00:00	Type:	Comprehensive		ve		
<b>Product Name:</b>	CCTV						
Complain:	backside outside 1 camera not working						
Technician Comment :	backside out side one no video issue resolved but temporary going on in nvr bcz one pair cable breck inform to kedar sir next time need to change cable camera off 21/3 /23						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	backside out side one no video issue resolved but temporary going on in nvr bcz one pair cable breck inform to kedar sir next time need to change cable camera off 21/3 /23						
Status History :	Date Time	Technician Name	Status	Remark Sign  backside out side one no video issue resolved but temporary going on in nvr bcz one pair cable breck inform to kedar sir next time need to change cable camera off 21/3 /23		Sign	
	08-04-2023 02:59:42	Ravi Rajbhar	Completed			Apply	
	08-04-2023 10:27:15	Ravi Rajbhar	New			-	
Previous Complain History	Date Time	Technician Name		Remark			
:	14-02-2023 03:03:33	Ravi Rajbhar		llege 2nd floor back side no video issue resolved and ok rking done recoding also going on in nvr			
	11-02-2023 10:17:13	Sonu Kumar	Batminton	Batminton area ip 6*6 box installed			