







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8477																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	8097384039																													
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																										
Ticket Type :	Complain	Date & Time :	02-06-2023 11:47:22																											
Vendor Details :																														
Company Name/Client Name :	Ritambhara Vishva Vidyapeeth - College	Customer's Mobile :	8097384039	Name :	Kedar Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	31-05-2021 12:00:00		Type :	Comprehensive																										
Product Name :	CCTV																													
Complain :	Outside 2 cameras off issue																													
Technician Comment :	One bullet camera out side c installed after repaired and working ok set also angel ip.192.168.1.10 Pass.admin																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	One bullet camera out side c installed after repaired and working ok set also angel ip.192.168.1.10 Pass.admin																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-06-2023 01:43:11</td><td>Atique Salmani</td><td>Completed</td><td>One bullet camera out side c installed after repaired and working ok set also angel ip.192.168.1.10 Pass.admin</td><td></td></tr><tr><td>10-06-2023 11:05:59</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>02-06-2023 05:03:57</td><td>Atique Salmani</td><td>Work Pending</td><td>192.168.1.61 camera issue resolved and 192.168.1.10 camera not becoz camera famale connector issue so collect camera for check and repair .</td><td></td></tr><tr><td>02-06-2023 11:47:48</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-06-2023 01:43:11	Atique Salmani	Completed	One bullet camera out side c installed after repaired and working ok set also angel ip.192.168.1.10 Pass.admin		10-06-2023 11:05:59	Atique Salmani	New		-	02-06-2023 05:03:57	Atique Salmani	Work Pending	192.168.1.61 camera issue resolved and 192.168.1.10 camera not becoz camera famale connector issue so collect camera for check and repair .		02-06-2023 11:47:48	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
10-06-2023 01:43:11	Atique Salmani	Completed	One bullet camera out side c installed after repaired and working ok set also angel ip.192.168.1.10 Pass.admin																											
10-06-2023 11:05:59	Atique Salmani	New		-																										
02-06-2023 05:03:57	Atique Salmani	Work Pending	192.168.1.61 camera issue resolved and 192.168.1.10 camera not becoz camera famale connector issue so collect camera for check and repair .																											
02-06-2023 11:47:48	Atique Salmani	New		-																										

Previous Complain History :	Date Time	Technician Name	Remark
	13-06-2023 10:48:59	Atique Salmani	There is requirement for payroll and salary calculation And near about 10 to 12 shift need to create And also employees code need to lock if any employee leave nobody can use employees code and nobody can punch by employee code .
	15-05-2023 12:41:01	Atique Salmani	Ppm done all out side camera also clean all working ok. One camera hub station insert water so need to changed bullet camera and some trees leaf coming front of camera main gate sontod to kedar sir for cut it .