Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status De	tails: VE9122						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob.	8097384039						
Technician Name :	Ravi Rajbhar		Technician :	Mobile	8080922965		
Ticket Type :	Complain Date & Time :		10-08-2023 02:17:02				
Vendor Details :							
Company Name/Client Name :	Ritambhara Vishva Vidyapeeth - School	Customer's Mobile :	8097384039)	Name :	Kedar Sir	
Address:							
Mumbai , , , , Ma	harashtra						
AMC Details:			_				
Expiry Date :	31-05-2021 12:00:00		Type:	Type:		Non-Comprehensive	
Product Name:	CCTV						
Complain:	2nd floor 10-12 cameras off issue						
Technician Comment :	school second floor one camera no video issue resloved and ok wprking done						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	school second floor one camera no video issue resloved and ok wprking done						
Status History :	Date Time Technician Name Status Remark		Sign				
	14-08-2023 12:32:39	Ravi Rajbhar	Completed	school second floor one camera no video issue resloved and ok wprking done			
	14-08-2023 10:37:03	Ravi Rajbhar	New			-	
	12-08-2023 02:48:37	Ravi Rajbhar	Work Pending	-		-	
	11-08-2023 03:51:21	Ravi Rajbhar	Completed	2 nd floor extension board fuse faulty so changed and also Poe switch faulty so insta aled new poe switch as stand by working all camera ok 1 camera painding need to recheck 2 nd floor stationery room .		y C	
	11-08-2023 11:43:40	Ravi Rajbhar	New			-	
	10-08-2023 02:17:08	Ravi Rajbhar	New			-	

Previous Complain History:

Date Time	Technician Name	Remark
08-09-2023 10:46:29	Munna Gupta	Second floor switch repair and return and installed. All cctv system working ok
19-08-2023 01:19:54	Ravi Rajbhar	back side one camera box cover fited