




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE9206																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	8097384039																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	18-08-2023 03:05:56																	
Vendor Details :																				
Company Name/Client Name :	Ritambhara Vishva Vidyapeeth - School	Customer's Mobile :	8097384039	Name :	Kedar Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	31-05-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	Stationery Room and class no. 204 camera off issue																			
Technician Comment :	School 2 cameras issue resolved by stationery recrimping camera emd and 204 Poe swich side all working ok.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	School 2 cameras issue resolved by stationery recrimping camera emd and 204 Poe swich side all working ok.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>19-08-2023 01:17:10</td><td>Atique Salmani</td><td>Completed</td><td>School 2 cameras issue resolved by stationery recrimping camera emd and 204 Poe swich side all working ok.</td><td></td></tr><tr><td>19-08-2023 11:47:51</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	19-08-2023 01:17:10	Atique Salmani	Completed	School 2 cameras issue resolved by stationery recrimping camera emd and 204 Poe swich side all working ok.		19-08-2023 11:47:51	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
19-08-2023 01:17:10	Atique Salmani	Completed	School 2 cameras issue resolved by stationery recrimping camera emd and 204 Poe swich side all working ok.																	
19-08-2023 11:47:51	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-09-2023 10:46:29</td><td>Munna Gupta</td><td>Second floor switch repair and return and installed. All cctv system working ok</td></tr><tr><td>19-08-2023 01:19:54</td><td>Ravi Rajbhar</td><td>back side one camera box cover fitted</td></tr></tbody></table>					Date Time	Technician Name	Remark	08-09-2023 10:46:29	Munna Gupta	Second floor switch repair and return and installed. All cctv system working ok	19-08-2023 01:19:54	Ravi Rajbhar	back side one camera box cover fitted						
Date Time	Technician Name	Remark																		
08-09-2023 10:46:29	Munna Gupta	Second floor switch repair and return and installed. All cctv system working ok																		
19-08-2023 01:19:54	Ravi Rajbhar	back side one camera box cover fitted																		