

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14577																																								
Priority :	Low																																							
Created By :	Admin - Apurva Vajaria																																							
Complaint Mob. No. :	9819121121																																							
Technician Name :	Pravin Jagade		Technician Mobile :	7262044153																																				
Ticket Type :	Complain	Date & Time :	23-04-2025 12:19:40																																					
Vendor Details :																																								
Company Name/Client Name :	KES International School	Customer's Mobile :	9819121121	Name :	Keval Sir																																			
Address :																																								
Mumbai , , , , Maharashtra																																								
AMC Details :																																								
Expiry Date :	01-01-1970 05:30:00		Type :																																					
Product Name :	CCTV																																							
Complain :	toilet side camera again off issue																																							
Technician Comment :	toilet camera on off ieesu not solved. cheking office.																																							
Complain Operator :	Desktop - Apurva Vajaria																																							
Remark :	toilet camera on off ieesu not solved. cheking office.																																							
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-05-2025 11:32:00</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr><tr><td>09-05-2025 11:03:58</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr><tr><td>08-05-2025 10:43:19</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr><tr><td>07-05-2025 10:39:32</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr><tr><td>23-04-2025 01:21:11</td><td>PravinJagade</td><td>Work Pending</td><td>toilet camera on off ieesu not solved. cheking office.</td><td></td></tr><tr><td>23-04-2025 12:28:28</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-05-2025 11:32:00	PravinJagade	New		-	09-05-2025 11:03:58	PravinJagade	New		-	08-05-2025 10:43:19	PravinJagade	New		-	07-05-2025 10:39:32	PravinJagade	New		-	23-04-2025 01:21:11	PravinJagade	Work Pending	toilet camera on off ieesu not solved. cheking office.		23-04-2025 12:28:28	PravinJagade	New		-
Date Time	Technician Name	Status	Remark	Sign																																				
10-05-2025 11:32:00	PravinJagade	New		-																																				
09-05-2025 11:03:58	PravinJagade	New		-																																				
08-05-2025 10:43:19	PravinJagade	New		-																																				
07-05-2025 10:39:32	PravinJagade	New		-																																				
23-04-2025 01:21:11	PravinJagade	Work Pending	toilet camera on off ieesu not solved. cheking office.																																					
23-04-2025 12:28:28	PravinJagade	New		-																																				
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>16-06-2025 04:19:48</td><td>ChandanYadav</td><td>out side work complete.one garda side camera install and road side camera connection problem and change the rj45 connecter and camera working ok. lift camera working power supply ieesu and change the supply and working ok.</td></tr><tr><td>22-05-2025 10:11:39</td><td>Atique Salmani</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	16-06-2025 04:19:48	ChandanYadav	out side work complete.one garda side camera install and road side camera connection problem and change the rj45 connecter and camera working ok. lift camera working power supply ieesu and change the supply and working ok.	22-05-2025 10:11:39	Atique Salmani																											
Date Time	Technician Name	Remark																																						
16-06-2025 04:19:48	ChandanYadav	out side work complete.one garda side camera install and road side camera connection problem and change the rj45 connecter and camera working ok. lift camera working power supply ieesu and change the supply and working ok.																																						
22-05-2025 10:11:39	Atique Salmani																																							