




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11611																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9819121121																			
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																
Ticket Type :	Complain	Date & Time :	10-05-2024 06:38:24																	
Vendor Details :																				
Company Name/Client Name :	Vajaria Enterprises	Customer's Mobile :	9819121121	Name :	Keval Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	EPABX																			
Complain :	Site: Mitsubishi BKC - Grandstream IPBX date time issue																			
Technician Comment :	2 phone line issue resoved reprogramming and date time issue pending																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	2 phone line issue resoved reprogramming and date time issue pending																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>11-05-2024 03:03:09</td><td>Siddhesh Chavan</td><td>Work Pending</td><td>2 phone line issue resoved reprogramming and date time issue pending</td><td></td></tr><tr><td>11-05-2024 10:57:04</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	11-05-2024 03:03:09	Siddhesh Chavan	Work Pending	2 phone line issue resoved reprogramming and date time issue pending		11-05-2024 10:57:04	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																
11-05-2024 03:03:09	Siddhesh Chavan	Work Pending	2 phone line issue resoved reprogramming and date time issue pending																	
11-05-2024 10:57:04	Siddhesh Chavan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>23-07-2024 10:56:46</td><td>ChandanYadav</td><td>Levender All camera working and one camera cable faulty levender loby change the cable. Lilly. 1.8 floor Refuges ariya camera working and cable faulty matter room cable joined chenge the cable and 8 floor Refuges ariya camera not working. 2. Back side camera damage. 3. Main gate back side camera working. 4.lobby camera change the cable and cable faulty. 5.Main gate back side two camera not working.one camera are working and one camera faulty cheking the office. 6.Main gate two new 4*4 box installation</td></tr><tr><td>17-07-2024 05:01:46</td><td>Siddhesh Chavan</td><td>phone date time setting done and all system working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	23-07-2024 10:56:46	ChandanYadav	Levender All camera working and one camera cable faulty levender loby change the cable. Lilly. 1.8 floor Refuges ariya camera working and cable faulty matter room cable joined chenge the cable and 8 floor Refuges ariya camera not working. 2. Back side camera damage. 3. Main gate back side camera working. 4.lobby camera change the cable and cable faulty. 5.Main gate back side two camera not working.one camera are working and one camera faulty cheking the office. 6.Main gate two new 4*4 box installation	17-07-2024 05:01:46	Siddhesh Chavan	phone date time setting done and all system working ok						
Date Time	Technician Name	Remark																		
23-07-2024 10:56:46	ChandanYadav	Levender All camera working and one camera cable faulty levender loby change the cable. Lilly. 1.8 floor Refuges ariya camera working and cable faulty matter room cable joined chenge the cable and 8 floor Refuges ariya camera not working. 2. Back side camera damage. 3. Main gate back side camera working. 4.lobby camera change the cable and cable faulty. 5.Main gate back side two camera not working.one camera are working and one camera faulty cheking the office. 6.Main gate two new 4*4 box installation																		
17-07-2024 05:01:46	Siddhesh Chavan	phone date time setting done and all system working ok																		