




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1980																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9819121121																																		
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																															
Ticket Type :	New Installation	Date & Time :	07-10-2020 10:00:25																																
Vendor Details :																																			
Company Name/Client Name :	Vajaria Enterprises	Customer's Mobile :	9819121121	Name :	Keval Sir																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	Fire																																		
Complain :	installation of Fire alarm system andheri - near wall street																																		
Technician Comment :	10 s. d. and 2hooter and 1 mcpi stalled and also 2zome agni fire panel and also intigration with socity fire panel tested by roshan sir socity fire alarm engeenear. check all detector blinking. and fire alarm system healthy.																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	10 s. d. and 2hooter and 1 mcpi stalled and also 2zome agni fire panel and also intigration with socity fire panel tested by roshan sir socity fire alarm engeenear. check all detector blinking. and fire alarm system healthy.																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-10-2020 08:09:33</td><td>Atique Salmani</td><td>Completed</td><td>10 s. d. and 2hooter and 1 mcpi stalled and also 2zome agni fire panel and also intigration with socity fire panel tested by roshan sir socity fire alarm engeenear. check all detector blinking. and fire alarm system healthy.</td><td></td></tr><tr><td>07-10-2020 10:13:21</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>07-10-2020 10:06:41</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>07-10-2020 10:02:32</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>07-10-2020 10:00:26</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-10-2020 08:09:33	Atique Salmani	Completed	10 s. d. and 2hooter and 1 mcpi stalled and also 2zome agni fire panel and also intigration with socity fire panel tested by roshan sir socity fire alarm engeenear. check all detector blinking. and fire alarm system healthy.		07-10-2020 10:13:21	Atique Salmani	New		-	07-10-2020 10:06:41	Atique Salmani	New		-	07-10-2020 10:02:32	Atique Salmani	New		-	07-10-2020 10:00:26	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																															
08-10-2020 08:09:33	Atique Salmani	Completed	10 s. d. and 2hooter and 1 mcpi stalled and also 2zome agni fire panel and also intigration with socity fire panel tested by roshan sir socity fire alarm engeenear. check all detector blinking. and fire alarm system healthy.																																
07-10-2020 10:13:21	Atique Salmani	New		-																															
07-10-2020 10:06:41	Atique Salmani	New		-																															
07-10-2020 10:02:32	Atique Salmani	New		-																															
07-10-2020 10:00:26	Atique Salmani	New		-																															

Previous Complain History :	Date Time	Technician Name	Remark
	24-10-2020 10:59:14	Neeraj Chauhan	
	23-10-2020 10:35:39	Ravi Rajbhar	CCTV camera survey done 10 camera with cabling 250- 300 meter and raunak heights 406 vdp out door camera issue resolved