

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE5228																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9819121121																																		
Technician Name :	Chandan Yadav		Technician Mobile :	9833262842																															
Ticket Type :	Complain	Date & Time :	16-04-2022 01:43:01																																
Vendor Details :																																			
Company Name/Client Name :	Vajaria Enterprises	Customer's Mobile :	9819121121	Name :	Keval Sir																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	CCTV																																		
Complain :	site: shaman motors vashi - hdd issue																																		
Technician Comment :	hard disk not support dvr and hard disk and dvr reparing to office.																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	hard disk not support dvr and hard disk and dvr reparing to office. repaired dvr and hard disk installed																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>30-04-2022 10:26:45</td><td>ChandanYadav</td><td>Completed</td><td></td><td>-</td></tr><tr><td>30-04-2022 10:25:12</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>16-04-2022 01:45:31</td><td>ChandanYadav</td><td>Work Pending</td><td>hard disk not support dvr and hard disk and dvr reparing to office.</td><td></td></tr><tr><td>16-04-2022 01:43:13</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>16-04-2022 01:43:01</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	30-04-2022 10:26:45	ChandanYadav	Completed		-	30-04-2022 10:25:12	ChandanYadav	New		-	16-04-2022 01:45:31	ChandanYadav	Work Pending	hard disk not support dvr and hard disk and dvr reparing to office.		16-04-2022 01:43:13	ChandanYadav	New		-	16-04-2022 01:43:01	ChandanYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																															
30-04-2022 10:26:45	ChandanYadav	Completed		-																															
30-04-2022 10:25:12	ChandanYadav	New		-																															
16-04-2022 01:45:31	ChandanYadav	Work Pending	hard disk not support dvr and hard disk and dvr reparing to office.																																
16-04-2022 01:43:13	ChandanYadav	New		-																															
16-04-2022 01:43:01	ChandanYadav	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>29-04-2022 04:16:18</td><td>ChandanYadav</td><td>8 channel dvr and 2 power supply . 8 camera installation .cctv working ok.</td></tr><tr><td>28-04-2022 01:45:50</td><td>Munna Gupta</td><td>I visit in suman tower for. intercom system. c- wing extension line R11 connector problem . New connector crimping problem resolve. intercom system working properly. There is a need to change the 4*4 box of all the cameras installed in the outside area.</td></tr></tbody></table>					Date Time	Technician Name	Remark	29-04-2022 04:16:18	ChandanYadav	8 channel dvr and 2 power supply . 8 camera installation .cctv working ok.	28-04-2022 01:45:50	Munna Gupta	I visit in suman tower for. intercom system. c- wing extension line R11 connector problem . New connector crimping problem resolve. intercom system working properly. There is a need to change the 4*4 box of all the cameras installed in the outside area.																					
Date Time	Technician Name	Remark																																	
29-04-2022 04:16:18	ChandanYadav	8 channel dvr and 2 power supply . 8 camera installation .cctv working ok.																																	
28-04-2022 01:45:50	Munna Gupta	I visit in suman tower for. intercom system. c- wing extension line R11 connector problem . New connector crimping problem resolve. intercom system working properly. There is a need to change the 4*4 box of all the cameras installed in the outside area.																																	