

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE5281																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9819121121																													
Technician Name :	Chandan Yadav		Technician Mobile :	9833262842																										
Ticket Type :	Complain	Date & Time :	23-04-2022 06:39:47																											
Vendor Details :																														
Company Name/Client Name :	Vajaria Enterprises	Customer's Mobile :	9819121121	Name :	Keval Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	Site-Ramada bandra- camera installation																													
Technician Comment :	work completed.																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	work completed.																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>30-04-2022 10:24:41</td><td>ChandanYadav</td><td>Completed</td><td>work completed.</td><td></td></tr><tr><td>23-04-2022 06:57:55</td><td>ChandanYadav</td><td>Work Pending</td><td>5 camera installation and 3 camera pending</td><td></td></tr><tr><td>23-04-2022 06:40:09</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>23-04-2022 06:39:47</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	30-04-2022 10:24:41	ChandanYadav	Completed	work completed.		23-04-2022 06:57:55	ChandanYadav	Work Pending	5 camera installation and 3 camera pending		23-04-2022 06:40:09	ChandanYadav	New		-	23-04-2022 06:39:47	ChandanYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																										
30-04-2022 10:24:41	ChandanYadav	Completed	work completed.																											
23-04-2022 06:57:55	ChandanYadav	Work Pending	5 camera installation and 3 camera pending																											
23-04-2022 06:40:09	ChandanYadav	New		-																										
23-04-2022 06:39:47	ChandanYadav	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>29-04-2022 04:16:18</td><td>ChandanYadav</td><td>8 channel dvr and 2 power supply . 8 camera installation .cctv working ok.</td></tr><tr><td>28-04-2022 01:45:50</td><td>Munna Gupta</td><td>I visit in suman tower for. intercom system. c- wing extension line R11 connector problem . New connector crimping problem resolve. intercom system working properly. There is a need to change the 4*4 box of all the cameras installed in the outside area.</td></tr></tbody></table>					Date Time	Technician Name	Remark	29-04-2022 04:16:18	ChandanYadav	8 channel dvr and 2 power supply . 8 camera installation .cctv working ok.	28-04-2022 01:45:50	Munna Gupta	I visit in suman tower for. intercom system. c- wing extension line R11 connector problem . New connector crimping problem resolve. intercom system working properly. There is a need to change the 4*4 box of all the cameras installed in the outside area.																
Date Time	Technician Name	Remark																												
29-04-2022 04:16:18	ChandanYadav	8 channel dvr and 2 power supply . 8 camera installation .cctv working ok.																												
28-04-2022 01:45:50	Munna Gupta	I visit in suman tower for. intercom system. c- wing extension line R11 connector problem . New connector crimping problem resolve. intercom system working properly. There is a need to change the 4*4 box of all the cameras installed in the outside area.																												