




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE5687</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9819121121																								
<b>Technician Name :</b>	Chandan Yadav		<b>Technician Mobile :</b>	9833262842																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	11-06-2022 11:43:44																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Vajaria Enterprises	Customer's Mobile :	9819121121	Name :	Keval Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
<b>Product Name :</b>	Intercom																								
<b>Complain :</b>	Raunak Heights H2 - 203/308/406/407/703/804/902/1105/1402/1804/1906 - intercom issue H3 - 507/602/1004 - intercom issue																								
<b>Technician Comment :</b>	203 working ok 406 flat lock 407 working ok and instrument problem 406 working ok and instrument problem 703 flat lock 804 working ok and instrument problem 902 flat lock 1105 working ok 1402 working ok and instrument problem 1806 flat lock 1904 flat lock H3 507 flat lok 602 working ok 1004 working ok 1605 working ok.																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	203 working ok 406 flat lock 407 working ok and instrument problem 406 working ok and instrument problem 703 flat lock 804 working ok and instrument problem 902 flat lock 1105 working ok 1402 working ok and instrument problem 1806 flat lock 1904 flat lock H3 507 flat lok 602 working ok 1004 working ok 1605 working ok.																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>11-06-2022 01:53:46</td><td>ChandanYadav</td><td>Completed</td><td>203 working ok 406 flat lock 407 working ok and instrument problem 406 working ok and instrument problem 703 flat lock 804 working ok and instrument problem 902 flat lock 1105 working ok 1402 working ok and instrument problem 1806 flat lock 1904 flat lock H3 507 flat lok 602 working ok 1004 working ok 1605 working ok.</td><td></td></tr><tr><td>11-06-2022 11:44:07</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>11-06-2022 11:43:44</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	11-06-2022 01:53:46	ChandanYadav	Completed	203 working ok 406 flat lock 407 working ok and instrument problem 406 working ok and instrument problem 703 flat lock 804 working ok and instrument problem 902 flat lock 1105 working ok 1402 working ok and instrument problem 1806 flat lock 1904 flat lock H3 507 flat lok 602 working ok 1004 working ok 1605 working ok.		11-06-2022 11:44:07	ChandanYadav	New		-	11-06-2022 11:43:44	ChandanYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																					
11-06-2022 01:53:46	ChandanYadav	Completed	203 working ok 406 flat lock 407 working ok and instrument problem 406 working ok and instrument problem 703 flat lock 804 working ok and instrument problem 902 flat lock 1105 working ok 1402 working ok and instrument problem 1806 flat lock 1904 flat lock H3 507 flat lok 602 working ok 1004 working ok 1605 working ok.																						
11-06-2022 11:44:07	ChandanYadav	New		-																					
11-06-2022 11:43:44	ChandanYadav	New		-																					

Previous Complain History :			
	Date Time	Technician Name	Remark
	06-06-2022 05:59:24	ChandanYadav	recording backup and intercom issu sole.
	02-06-2022 04:29:39	ChandanYadav	one camera installation done and one not working and brek the cakble change the cakble.