## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE10654 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9821069152 **No. : Technician Name Technician Mobile** 7489567735 Shiva Meena Complain 29-01-2024 01:56:00 **Ticket Type : Date & Time : Vendor Details :** Swapnalok CHS Customer's Mobile 9821069152 Kishor Bhai Company Name : Name/Client Name Address : Mumbai,,,, Maharashtra **AMC Details :** 31-05-2021 12:00:00 Comprehensive Expiry Date : Type : **Product Name :** CCTV **Complain**: 1)B-701 VDP issue 2)A and B wing lift camera off issue B wing 701 video door phone issue resolved and ok working done and a wing lift one lift **Technician Comment**: cmaera work pending bcz lift door not open and B wing both lift no video issue resolved and ok working done both lift BNC Pin change Complain Desktop - Apurva Vajaria **Operator** : B wing 701 video door phone issue resolved and ok working done and a wing lift one lift **Remark** : cmaera work pending bcz lift door not open and B wing both lift no video issue resolved and ok working done both lift BNC Pin change **Status History : Technician Name Date Time** Status Remark Sign 02-02-2024 11:31:01 Shiva Meena New 30-01-2024 01:03:32 Shiva Meena Client B wing 701 video door phone Kalh Side issue resolved and ok working done and a wing lift one lift cmaera work pending bcz lift door not open and B wing both lift no video issue resolved and ok working done both lift BNC Pin change 30-01-2024 10:25:23 Shiva Meena New 29-01-2024 01:56:17 Shiva Meena New Previous **Technician Name Date Time** Remark **Complain History** 16-02-2024 10:18:14 Atique Salmani A wing lift SMPS missing so installed new SMPS but there is : issue in also camera so collect for repair.painding . 03-02-2024 10:40:22 Shiva Meena TV Issue solve done