




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE2530</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9821069152																								
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	04-01-2021 04:55:11																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Swapnalok CHS	<b>Customer's Mobile :</b>	9821069152	<b>Name :</b>	Kishor Bhai																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	31-05-2021 12:00:00		<b>Type :</b>	Comprehensive																					
<b>Product Name :</b>	Intercom																								
<b>Complain :</b>	ringing issue - 701/b																								
<b>Technician Comment :</b>	b 701 intercom issue resolved after find iut the cable there is issue from duct jio person has remooved the cable now its working ok.																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	b 701 intercom issue resolved after find iut the cable there is issue from duct jio person has remooved the cable now its working ok.																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>04-01-2021 07:01:40</td><td>Atique Salmani</td><td>Completed</td><td>b 701 intercom issue resolved after find iut the cable there is issue from duct jio person has remooved the cable now its working ok.</td><td></td></tr><tr><td>04-01-2021 04:55:25</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>04-01-2021 04:55:11</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	04-01-2021 07:01:40	Atique Salmani	Completed	b 701 intercom issue resolved after find iut the cable there is issue from duct jio person has remooved the cable now its working ok.		04-01-2021 04:55:25	Atique Salmani	New		-	04-01-2021 04:55:11	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
04-01-2021 07:01:40	Atique Salmani	Completed	b 701 intercom issue resolved after find iut the cable there is issue from duct jio person has remooved the cable now its working ok.																						
04-01-2021 04:55:25	Atique Salmani	New		-																					
04-01-2021 04:55:11	Atique Salmani	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-08-2023 10:07:58</td><td>Siddhesh Chavan</td><td></td></tr><tr><td>17-07-2023 10:38:27</td><td>Kalpesh SubhashGurav</td><td>B Wing 403 Intercom Issue Solved</td></tr></tbody></table>					Date Time	Technician Name	Remark	08-08-2023 10:07:58	Siddhesh Chavan		17-07-2023 10:38:27	Kalpesh SubhashGurav	B Wing 403 Intercom Issue Solved											
Date Time	Technician Name	Remark																							
08-08-2023 10:07:58	Siddhesh Chavan																								
17-07-2023 10:38:27	Kalpesh SubhashGurav	B Wing 403 Intercom Issue Solved																							