

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3632																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9821069152																																		
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																															
Ticket Type :	Complain	Date & Time :	13-08-2021 04:47:47																																
Vendor Details :																																			
Company Name/Client Name :	Swapnalok CHS	Customer's Mobile :	9821069152	Name :	Kishor Bhai																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	31-05-2021 12:00:00		Type :	Comprehensive																															
Product Name :	Intercom																																		
Complain :	A wing - 601 & b wing - 503 intercom issue																																		
Technician Comment :	a wing 601 602: joined flat and cable check and new program and new flat no 602 and Clint phone issue																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	a wing 601 602: joined flat and cable check and new program and new flat no 602 and Clint phone issue																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>20-08-2021 01:54:05</td><td>Siddhesh Chavan</td><td>Completed</td><td>a wing 601 602: joined flat and cable check and new program and new flat no 602 and Clint phone issue</td><td></td></tr><tr><td>20-08-2021 10:22:32</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>13-08-2021 07:22:55</td><td>Siddhesh Chavan</td><td>Work Pending</td><td>b wing 503 intercom issue resolved and A wing 601 flat lock</td><td></td></tr><tr><td>13-08-2021 04:48:13</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>13-08-2021 04:47:47</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	20-08-2021 01:54:05	Siddhesh Chavan	Completed	a wing 601 602: joined flat and cable check and new program and new flat no 602 and Clint phone issue		20-08-2021 10:22:32	Siddhesh Chavan	New		-	13-08-2021 07:22:55	Siddhesh Chavan	Work Pending	b wing 503 intercom issue resolved and A wing 601 flat lock		13-08-2021 04:48:13	Siddhesh Chavan	New		-	13-08-2021 04:47:47	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																															
20-08-2021 01:54:05	Siddhesh Chavan	Completed	a wing 601 602: joined flat and cable check and new program and new flat no 602 and Clint phone issue																																
20-08-2021 10:22:32	Siddhesh Chavan	New		-																															
13-08-2021 07:22:55	Siddhesh Chavan	Work Pending	b wing 503 intercom issue resolved and A wing 601 flat lock																																
13-08-2021 04:48:13	Siddhesh Chavan	New		-																															
13-08-2021 04:47:47	Siddhesh Chavan	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-08-2023 10:07:58</td><td>Siddhesh Chavan</td><td></td></tr><tr><td>17-07-2023 10:38:27</td><td>Kalpesh SubhashGurav</td><td>B Wing 403 Intercom Issue Solved</td></tr></tbody></table>					Date Time	Technician Name	Remark	08-08-2023 10:07:58	Siddhesh Chavan		17-07-2023 10:38:27	Kalpesh SubhashGurav	B Wing 403 Intercom Issue Solved																					
Date Time	Technician Name	Remark																																	
08-08-2023 10:07:58	Siddhesh Chavan																																		
17-07-2023 10:38:27	Kalpesh SubhashGurav	B Wing 403 Intercom Issue Solved																																	