




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE9618</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9821069152																			
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	25-09-2023 11:13:31																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	Swapnalok CHS	Customer's Mobile :	9821069152	Name :	Kishor Bhai															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
Expiry Date :	31-05-2021 12:00:00		Type :	Comprehensive																
<b>Product Name :</b>	Intercom																			
<b>Complain :</b>	B-102 intercom not working																			
<b>Technician Comment :</b>	B102 issue resolved checked from floor junction line was break so recocoonet afr findout the cable working ok.																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	B102 issue resolved checked from floor junction line was break so recocoonet afr findout the cable working ok.																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>25-09-2023 02:52:36</td><td>Atique Salmani</td><td>Completed</td><td>B102 issue resolved checked from floor junction line was break so recocoonet afr findout the cable working ok.</td><td></td></tr><tr><td>25-09-2023 12:32:06</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	25-09-2023 02:52:36	Atique Salmani	Completed	B102 issue resolved checked from floor junction line was break so recocoonet afr findout the cable working ok.		25-09-2023 12:32:06	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
25-09-2023 02:52:36	Atique Salmani	Completed	B102 issue resolved checked from floor junction line was break so recocoonet afr findout the cable working ok.																	
25-09-2023 12:32:06	Atique Salmani	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>21-09-2023 01:13:28</td><td>Siddhesh Chavan</td><td>biometric dives ruten install and one person finger add done and finger print senser working OK</td></tr><tr><td>18-09-2023 02:30:29</td><td>Ravi Rajbhar</td><td>B wing lobby biometric divice punching issue resloved and ok working done and old logs data delete</td></tr></tbody></table>					Date Time	Technician Name	Remark	21-09-2023 01:13:28	Siddhesh Chavan	biometric dives ruten install and one person finger add done and finger print senser working OK	18-09-2023 02:30:29	Ravi Rajbhar	B wing lobby biometric divice punching issue resloved and ok working done and old logs data delete						
Date Time	Technician Name	Remark																		
21-09-2023 01:13:28	Siddhesh Chavan	biometric dives ruten install and one person finger add done and finger print senser working OK																		
18-09-2023 02:30:29	Ravi Rajbhar	B wing lobby biometric divice punching issue resloved and ok working done and old logs data delete																		