Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE10266 **Priority** : Low **Created By :** Admin - Apurva Vajaria Complaint 9820606496 Mob. No. : Technician Siddhesh Chavan **Technician Mobile :** 8080922985 Name : Complain 14-12-2023 10:25:59 **Ticket Type :** Date & Time : **Vendor Details :** Samet Sikhar Customer's Mobile : Company 9820606496 Name : Kothari Name/Client Mahal Society Name : Address : Mumbai,,,, Maharashtra **AMC Details :** Expiry Date : 01-01-1970 05:30:00 Type : **Product Name** VDP 22 flats which are not working need to check **Complain**: **Technician** lobby penal speak change and repair and install and aslo flats check **Comment :** Desktop - Apurva Vajaria Complain **Operator** : lobby penal speak change and repair and install and aslo flats check **Remark** :

Status History Technician					
:	Date Time	Technician Name	Status	Remark	Sign
	04-01-2024 07:12:39	Siddhesh Chavan	New		-
	21-12-2023 02:35:46	Siddhesh Chavan	Work Pending	lobby penal speak change and repair and install and aslo flats check	ADARAI
	21-12-2023 01:39:41	Siddhesh Chavan	New		-
	14-12-2023 06:37:35	Siddhesh Chavan	Work Pending	101 = working ok 102 = working ok 103 = working ok 104 = not working =because door lock 201 = working ok 202 = not working =door lock 203 = working ok 204 = working ok 301 = working ok 302 = not working = door lock 303 = working ok 304 = working ok 401 = working ok 402 = working ok 403 = working ok 404 = working ok 501 = not a flat refuse area 502 = not working vdp and out door take to office for checking for checking 7506746966 503 = not working = nc01 missing need to check cable vdp speaker, problem 504 = working ok 601 = working ok 602 = working ok 603 = not working = nc01 joint 604 = not working = vdp lobby cable issue 701 = working ok 702 = working ok 703 = working ok 704 = working ok 801 = working ok 802 = working ok 803 = working ok 804 = working ok 901 = not working = door lock 902 = working ok 903 = working ok 904 = not working = lobby cable issue 1001 = working ok 1002 = working ok 1003 = not working = lobby cable issue 1004 = working ok 1101 = working ok 1102 = working ok 1103 = working ok 1102 = working ok 1203 = not working = lobby cable issue 1204 = not a flat refuse area 1202 = working ok 1203 = not working = lobby cable issue 1204 = not working = door lock 1301 = not working ok 1402 = working ok 1403 = working ok 1404 = working ok 1501 = working ok 1404 = working ok 1501 = working ok 1502 = working ok 1503 = working ok 1504 = working ok 1601 = working ok 1602 = working ok 1603 1604 = working ok 1602 = morking ok 1603 1604 = working ok 1602 = morking ok 1603 1604 = working ok 1704 = working ok 1801 = not working = door lock 1802 = working ok 1803 = not working = lobby cable need to check 1702 = not working = door lock 1703 = working ok 1602 = working ok 1801 = not working = door lock 1802 = working ok 1803 = not working = door lock 1804 = not working = door lock 1802 = working ok 1803 = not working = door lock 1804 = not working = door lock 1802 = working ok 1803 = not working = door lock 1804 = not working = door lock 1801 = working ok 1803 = not working ok lobby panel speaker issue and lobby pa	Althout
	14-12-2023 10:26:06	Siddhesh Chavan	New		-
Previous Complain			ician Name	Remark	
History :			esh Chavan	o flats lobby video issue resolved 804 lobby video issue solved	
	30-11-2023 10:4	3:01 Siddh	esh Chavan	All system check done	