

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4167																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820606496																								
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																					
Ticket Type :	Complain	Date & Time :	02-11-2021 10:19:41																						
Vendor Details :																									
Company Name/Client Name :	Samdeshekhar Society	Customer's Mobile :	9820606496	Name :	Kothari																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	VDP																								
Complain :	Flat no. 403 - VDP Survey																								
Technician Comment :	vdp faulty and out door camera and nc-01 missing Clint have new video door phone																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	vdp faulty and out door camera and nc-01 missing Clint have new video door phone																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>02-11-2021 10:26:36</td><td>Siddhesh Chavan</td><td>Completed</td><td>vdp faulty and out door camera and nc-01 missing Clint have new video door phone</td><td></td></tr><tr><td>02-11-2021 10:22:58</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>02-11-2021 10:19:42</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	02-11-2021 10:26:36	Siddhesh Chavan	Completed	vdp faulty and out door camera and nc-01 missing Clint have new video door phone		02-11-2021 10:22:58	Siddhesh Chavan	New		-	02-11-2021 10:19:42	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
02-11-2021 10:26:36	Siddhesh Chavan	Completed	vdp faulty and out door camera and nc-01 missing Clint have new video door phone																						
02-11-2021 10:22:58	Siddhesh Chavan	New		-																					
02-11-2021 10:19:42	Siddhesh Chavan	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>15-02-2022 10:10:18</td><td>Siddhesh Chavan</td><td>1402 vdp video issue resolved and working ok</td></tr><tr><td>14-02-2022 06:55:14</td><td>Siddhesh Chavan</td><td>7 th floor to 19 floor lobby video issue resolved and 7 th floor distributor side rj45 patch cord change and all working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	15-02-2022 10:10:18	Siddhesh Chavan	1402 vdp video issue resolved and working ok	14-02-2022 06:55:14	Siddhesh Chavan	7 th floor to 19 floor lobby video issue resolved and 7 th floor distributor side rj45 patch cord change and all working ok											
Date Time	Technician Name	Remark																							
15-02-2022 10:10:18	Siddhesh Chavan	1402 vdp video issue resolved and working ok																							
14-02-2022 06:55:14	Siddhesh Chavan	7 th floor to 19 floor lobby video issue resolved and 7 th floor distributor side rj45 patch cord change and all working ok																							