

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE5064																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820606496																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	23-03-2022 07:37:56																						
Vendor Details :																									
Company Name/Client Name :	Samdeshekhar Society	Customer's Mobile :	9820606496	Name :	Kothari																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	VDP																								
Complain :	Above 10th floor vdp voice issue																								
Technician Comment :	9 15. 1st all floor restart supply but 9 floor power code need to changed all working ok.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	9 15. 1st all floor restart supply but 9 floor power code need to changed all working ok.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>23-03-2022 08:20:59</td><td>Atique Salmani</td><td>Completed</td><td>9 15. 1st all floor restart supply but 9 floor power code need to changed all working ok.</td><td></td></tr><tr><td>23-03-2022 07:38:20</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>23-03-2022 07:37:56</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	23-03-2022 08:20:59	Atique Salmani	Completed	9 15. 1st all floor restart supply but 9 floor power code need to changed all working ok.		23-03-2022 07:38:20	Atique Salmani	New		-	23-03-2022 07:37:56	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
23-03-2022 08:20:59	Atique Salmani	Completed	9 15. 1st all floor restart supply but 9 floor power code need to changed all working ok.																						
23-03-2022 07:38:20	Atique Salmani	New		-																					
23-03-2022 07:37:56	Atique Salmani	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>15-02-2022 10:10:18</td><td>Siddhesh Chavan</td><td>1402 vdp video issue resolved and working ok</td></tr><tr><td>14-02-2022 06:55:14</td><td>Siddhesh Chavan</td><td>7 th floor to 19 floor lobby video issue resolved and 7 th floor distributor side rj45 patch cord change and all working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	15-02-2022 10:10:18	Siddhesh Chavan	1402 vdp video issue resolved and working ok	14-02-2022 06:55:14	Siddhesh Chavan	7 th floor to 19 floor lobby video issue resolved and 7 th floor distributor side rj45 patch cord change and all working ok											
Date Time	Technician Name	Remark																							
15-02-2022 10:10:18	Siddhesh Chavan	1402 vdp video issue resolved and working ok																							
14-02-2022 06:55:14	Siddhesh Chavan	7 th floor to 19 floor lobby video issue resolved and 7 th floor distributor side rj45 patch cord change and all working ok																							