





Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7560					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9820606496				
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985	
Ticket Type :	Complain	Date & Time :	07-02-2023 10:22:04		
Vendor Details :					
Company Name/Client Name :	Samdeshekhar Society	Customer's Mobile :	9820606496	Name :	Kothari
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	VDP				
Complain :	need to do 5-6 flat vdp issue				
Technician Comment :	1004 install new vdp and lobby video working .				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	1004 install new vdp and lobby video working .				

Status History :	Date Time	Technician Name	Status	Remark	Sign
	21-02-2023 05:38:24	Siddhesh Chavan	Completed	1004 install new vdp and lobby video working .	
	21-02-2023 04:48:22	Siddhesh Chavan	New		-
	20-02-2023 10:40:38	Siddhesh Chavan	New		-
	15-02-2023 01:01:39	Siddhesh Chavan	Work Pending	1603 vdp install and working ok 1404 = vdp install and working ok 1004 = door lock.	
	15-02-2023 01:01:39	Siddhesh Chavan	Work Pending	1603 vdp install and working ok 1404 = vdp install and working ok 1004 = door lock.	
	15-02-2023 12:41:09	Siddhesh Chavan	New		-
	07-02-2023 05:06:29	Siddhesh Chavan	Work Pending	1803 = lobby cable issue 1804 = lobby cable issue 1701 = lobby cable issue 1703 = working ok 1404 = screen mic issue screen take to office for checking 1301 = vdp not install 1202 = door lock 1004 = vdp voice issue vdp take to office 8369404892 904 = lobby cable issue 804 = working ok 604 = lobby cable issue 503 = door lock 201 = working ok 1604 = vdp 1 st port issue vdp take to office for checking	
	07-02-2023 10:22:58	Siddhesh Chavan	New		-
Previous Complain History :	Date Time	Technician Name	Remark		
	24-01-2023 05:54:53	Siddhesh Chavan	vdp bell issue resolved because vdp side do not disturab enable and satting disable and working ok and lobby cable issue		
	24-01-2023 05:53:58	Siddhesh Chavan	vdp working ok lobby video working ok ding dong bell issue		