

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3020																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820052929																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	Call Basis	Date & Time :	03-05-2021 10:04:33																						
Vendor Details :																									
Company Name/Client Name :	Multivision Technologies	Customer's Mobile :	9820052929	Name :	Lalit Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	EPABX																								
Complain :	lalji pada site																								
Technician Comment :	c wing 2002 a wing 404 a wing security tebal display issue resolved																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	c wing 2002 a wing 404 a wing security tebal display issue resolved																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>03-05-2021 11:04:34</td><td>Ravi Rajbhar</td><td>Completed</td><td>c wing 2002 a wing 404 a wing security tebal display issue resolved</td><td></td></tr><tr><td>03-05-2021 10:04:44</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>03-05-2021 10:04:34</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	03-05-2021 11:04:34	Ravi Rajbhar	Completed	c wing 2002 a wing 404 a wing security tebal display issue resolved		03-05-2021 10:04:44	Ravi Rajbhar	New		-	03-05-2021 10:04:34	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
03-05-2021 11:04:34	Ravi Rajbhar	Completed	c wing 2002 a wing 404 a wing security tebal display issue resolved																						
03-05-2021 10:04:44	Ravi Rajbhar	New		-																					
03-05-2021 10:04:34	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>30-12-2021 10:15:21</td><td>Atique Salmani</td><td>screen saver time set on never and start and end time also set now working ok..</td></tr><tr><td>13-08-2021 04:50:15</td><td>Ravi Rajbhar</td><td>sky link ephax system check but one MTNL line out side off and one MTNL line ok working directl</td></tr></tbody></table>					Date Time	Technician Name	Remark	30-12-2021 10:15:21	Atique Salmani	screen saver time set on never and start and end time also set now working ok..	13-08-2021 04:50:15	Ravi Rajbhar	sky link ephax system check but one MTNL line out side off and one MTNL line ok working directl											
Date Time	Technician Name	Remark																							
30-12-2021 10:15:21	Atique Salmani	screen saver time set on never and start and end time also set now working ok..																							
13-08-2021 04:50:15	Ravi Rajbhar	sky link ephax system check but one MTNL line out side off and one MTNL line ok working directl																							