




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE10462																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9930943918																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	06-01-2024 03:44:08																	
Vendor Details :																				
Company Name/Client Name :	St Joseph	Customer's Mobile :	9930943918	Name :	Levon															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	DVR 153 (5th Floor) not showing in local as well as network																			
Technician Comment :	Dvr nmbr 153 issue resolved by used new pachcode with 2 tk 45 connector used And kg section one outdoor camera off so coming beep sound changed BNC dc from camera end issue resolved working ok.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Dvr nmbr 153 issue resolved by used new pachcode with 2 tk 45 connector used And kg section one outdoor camera off so coming beep sound changed BNC dc from camera end issue resolved working ok.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-01-2024 11:52:18</td><td>Atique Salmani</td><td>Completed</td><td>Dvr nmbr 153 issue resolved by used new pachcode with 2 tk 45 connector used And kg section one outdoor camera off so coming beep sound changed BNC dc from camera end issue resolved working ok.</td><td></td></tr><tr><td>06-01-2024 06:32:23</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-01-2024 11:52:18	Atique Salmani	Completed	Dvr nmbr 153 issue resolved by used new pachcode with 2 tk 45 connector used And kg section one outdoor camera off so coming beep sound changed BNC dc from camera end issue resolved working ok.		06-01-2024 06:32:23	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
08-01-2024 11:52:18	Atique Salmani	Completed	Dvr nmbr 153 issue resolved by used new pachcode with 2 tk 45 connector used And kg section one outdoor camera off so coming beep sound changed BNC dc from camera end issue resolved working ok.																	
06-01-2024 06:32:23	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>02-01-2024 10:28:03</td><td>Siddhesh Chavan</td><td>bus no 10 DVR working OK all camera OK recoding ok</td></tr><tr><td>20-12-2023 05:41:25</td><td>Sonu Kumar</td><td>Ground floor camera no 2 off issue resolved 1 bnc conector change all working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	02-01-2024 10:28:03	Siddhesh Chavan	bus no 10 DVR working OK all camera OK recoding ok	20-12-2023 05:41:25	Sonu Kumar	Ground floor camera no 2 off issue resolved 1 bnc conector change all working ok						
Date Time	Technician Name	Remark																		
02-01-2024 10:28:03	Siddhesh Chavan	bus no 10 DVR working OK all camera OK recoding ok																		
20-12-2023 05:41:25	Sonu Kumar	Ground floor camera no 2 off issue resolved 1 bnc conector change all working ok																		