Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE11338 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9930943918 **No. : Technician** Atique Salmani **Technician Mobile** 8080922984 Name : Complain Date & Time : 08-04-2024 04:33:12 **Ticket Type : Vendor Details :** Customer's Mobile 9930943918 Company St Joseph Name : Levon Name/Client Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 31-03-2021 12:00:00 Expiry Date : Type : Non-Comprehensive **Product Name :** CCTV **Complain**: 22nd April need to send at 10am Bus no 8 All cameras, mDVR, wires to be removed 8 nmbr bus mobile dvr remooved and hand over to Leone sir and keep it in 4 th floor computer **Technician Comment** : lab 3 box 4 cameras one mobile dvr with all connectors . Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 8 nmbr bus mobile dvr remooved and hand over to Leone sir and keep it in 4 th floor computer lab 3 box 4 cameras one mobile dvr with all connectors . **Status History : Date Time Technician Name** Status Remark Sign 22-04-2024 Atique Salmani Completed 8 nmbr bus mobile dvr remooved N 12:28:01 and hand over to Leone sir and keep it in 4 th floor computer lab 3 box 4 cameras one mobile dvr with all connectors . 20-04-2024 Atique Salmani New 05:33:41 **Previous** Technician Date Time Remark Complain Name **History** : 24-06-2024 Neeraj 1.Nvr 156 one ip camera issue resolved camera side power cable 11:12:20 Chauhan reaction 2.dvr 157 Main gate camera reconnection and box change 3.dvr 158 class room camera issue resolved dvr side reconnection 4.159 new lift camera power supply on and camera issue resolved 5.161 camera 2 and 8 disturbance issue resolved 6. Dvr 163 2 camera disturbance issue resolved 7.165 pending 8.kg section ip camera working ok 9. New ip camera sifting done 20-06-2024 4/4 box 5 nos install and lift camera check power supply issue and Neerai 12:35:14 Chauhan out side 1 camera pipe fittings and 3 Camera angle set