Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE11938 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9930943918 **No. :** Technician Neeraj Chauhan **Technician Mobile** 8898885764 Name : Complain Date & Time : 20-06-2024 12:35:14 **Ticket Type : Vendor Details :** 9930943918 Company Customer's Mobile St Joseph Name : Levon Name/Client Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 31-03-2021 12:00:00 Non-Comprehensive Expiry Date : Type : **Product Name :** CCTV 1) Main gate side camera 5 box need to change 2) 2 camera issue need to check 3) 153 dVR **Complain** : offline 4) 7th floor newly dome camera need to shift according to Leone sir 5)163 camera number 2 need to collect Technician 4/4 box 5 nos install and lift camera check power supply issue and out side 1 camera pipe **Comment**: fittings and 3 Camera angle set Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 4/4 box 5 nos install and lift camera check power supply issue and out side 1 camera pipe fittings and 3 Camera angle set **Status History : Date Time Technician Name Status** Remark Sign 25-06-2024 01:32:59 Neeraj Chauhan Completed 20-06-2024 05:28:02 Neeraj Chauhan Work Pending 4/4 box 5 nos install and lift camera check power supply issue and out side 1 camera pipe fittings and 3 Camera angle set 20-06-2024 12:35:22 Neeraj Chauhan New

Previous Complain History :	Date Time	Technician Name	Remark
	24-06-2024 11:12:20	Neeraj Chauhan	1.Nvr 156 one ip camera issue resolved camera side power cable reaction 2.dvr 157 Main gate camera reconnection and box change 3.dvr 158 class room camera issue resolved dvr side reconnection 4.159 new lift camera power supply on and camera issue resolved 5.161 camera 2 and 8 disturbance issue resolved 6. Dvr 163 2 camera disturbance issue resolved 7.165 pending 8.kg section ip camera working ok 9. New ip camera sifting done
	15-06-2024 10:56:26	Siddhesh Chavan	6 no bus hdd change and recoding working ok