Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : $| \mathbf{W} :$ www.vallabhenterprises.com $\mathbf{E} :$ vallabhsecure@yahoo.co.in

Service Status Details : VE1261											
Priority :	High										
Created By :	Admin - Apurva Vajaria										
Complaint Mob. No. :	9930943918										
Technician Name :	Sachin Pawar		Technician Mobile :	8080922981							
Ticket Type :	Complain Date & Time :		28-02-2020 06:09:35	:09:35							
Vendor Details	•		_								
Company Name/Client Name :	St Joseph	Customer's Mobile :	9930943918	Name :	Levon						
Address :											
Mumbai , , , , Maharashtra											
AMC Details :											
Expiry Date :	31-03-2020 12:00:	00	Type :	Non-Comprehensive							
Product Name :	CCTV										
Complain :	bus no : 8 need to remover one camera hikvision bus email alert to be done										
Technician Comment :	[29/02, 6:29 pm] Sachin Dharpawar: New bus no 2 installation done ???? [29/02, 6:30 pm] Sachin Dharpawar: Bus no 7 new power supply cable installed by electrician [29/02, 6:30 pm] Sachin Dharpawar: Bus no 14 one camera connectro loose so resolved. [29/02, 6:31 pm] Sachin Dharpawar: Bus no 12 power cable need to install by electrician in 2 days. [29/02, 6:32 pm] Sachin Dharpawar: Hikvision m dvr email settings already done but today also rechecked and its working. [29/02, 6:32 pm] Sachin Dharpawar: Bus no 8 need to installed new camera as discussed with levon sir and falguni madam [29/02, 6:36 pm] Sachin Dharpawar: Bus no 9 and bus no 10 sim data plan is over so device is getting offline in server side Also informed to levon sir he will check.										
Complain Operator :	Desktop - Apurva Vajaria										
Remark :	[29/02, 6:29 pm] Sachin Dharpawar: New bus no 2 installation done ???? [29/02, 6:30 pm] Sachin Dharpawar: Bus no 7 new power supply cable installed by electrician [29/02, 6:30 pm] Sachin Dharpawar: Bus no 14 one camera connectro loose so resolved. [29/02, 6:31 pm] Sachin Dharpawar: Bus no 12 power cable need to install by electrician in 2 days. [29/02, 6:32 pm] Sachin Dharpawar: Hikvision m dvr email settings already done but today also rechecked and its working. [29/02, 6:32 pm] Sachin Dharpawar: Bus no 8 need to installed new camera as discussed with levon sir and falguni madam [29/02, 6:36 pm] Sachin Dharpawar: Bus no 9 and bus no 10 sim data plan is over so device is getting offline in server side Also informed to levon sir he will check.										

Status History :	Date Time	Technician Name		Status		Remark	Sign
	29-02-2020 06:39:28	SachinPa	chinPawar		oleted	[29/02, 6:29 pm] Sachin Dharpawar: New bus no 2 installation done ???? [29/02, 6:30 pm] Sachin Dharpawar: Bus no 7 new power supply cable installed by electrician [29/02, 6:30 pm] Sachin Dharpawar: Bus no 14 one camera connectro loose so resolved. [29/02, 6:31 pm] Sachin Dharpawar: Bus no 12 power cable need to install by electrician in 2 days. [29/02, 6:32 pm] Sachin Dharpawar: Hikvision m dvr email settings already done but today also rechecked and its working. [29/02, 6:32 pm] Sachin Dharpawar: Bus no 8 need to installed new camera as discussed with levon sir and falguni madam [29/02, 6:36 pm] Sachin Dharpawar: Bus no 9 and bus no 10 sim data plan is over so device is getting offline in server side Also informed to levon sir he will check.	
	29-02-2020 01:47:48	SachinPawar		New			-
	28-02-2020 06:09:36	SachinPa	awar	New			-
Previous Complain	Date Time	te Time Technician		Name		Remark	
History :	04-07-2020 11:17	020 11:17:07 AnilYadav			1) 10 dvr and 5 IP camera again and again offline issue solve 2 IP cameras not working complain solve also. 3) 1 IP camera find out after 8ch NVR in added. 4) one IP camera password after add in NVR.		camera IP
	05-06-2020 02:45	5:49 Sid	Siddhesh Chavan		Remove fisheye camera and nvr		