

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14078															
Priority :	Low														
Created By :	Admin - Apurva Vajaria														
Complaint Mob. No. :	9930943918														
Technician Name :	Anil Yadav		Technician Mobile :	8090436743											
Ticket Type :	New Installation	Date & Time :	15-02-2025 12:21:56												
Vendor Details :															
Company Name/Client Name :	St Joseph	Customer's Mobile :	9930943918	Name :	Levon										
Address :															
Mumbai , , , , Maharashtra															
AMC Details :															
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive											
Product Name :	CCTV														
Complain :	2 IP Dome and 2 HD Bullet is to be replaced.. and approx 100 mtrs cabling														
Technician Comment :															
Complain Operator :	Desktop - Apurva Vajaria														
Remark :															
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>15-02-2025 12:22:09</td><td>Anil Yadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	15-02-2025 12:22:09	Anil Yadav	New		-
Date Time	Technician Name	Status	Remark	Sign											
15-02-2025 12:22:09	Anil Yadav	New		-											
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-04-2025 05:00:29</td><td>Siddhesh Chavan</td><td>ground 2 camera sifting done in bracket and back side camera issue resoved</td></tr><tr><td>05-04-2025 05:15:03</td><td>Siddhesh Chavan</td><td>161 camera no 2 video issue resoved main gate and back gate fitting check ane update Levon Sir</td></tr></tbody></table>					Date Time	Technician Name	Remark	08-04-2025 05:00:29	Siddhesh Chavan	ground 2 camera sifting done in bracket and back side camera issue resoved	05-04-2025 05:15:03	Siddhesh Chavan	161 camera no 2 video issue resoved main gate and back gate fitting check ane update Levon Sir	
Date Time	Technician Name	Remark													
08-04-2025 05:00:29	Siddhesh Chavan	ground 2 camera sifting done in bracket and back side camera issue resoved													
05-04-2025 05:15:03	Siddhesh Chavan	161 camera no 2 video issue resoved main gate and back gate fitting check ane update Levon Sir													