




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14451																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9930943918																			
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																
Ticket Type :	Complain	Date & Time :	08-04-2025 05:00:29																	
Vendor Details :																				
Company Name/Client Name :	St Joseph	Customer's Mobile :	9930943918	Name :	Levon															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	1)Ground site 2 camera need to shift 2)main school backside 1 camera need to fix																			
Technician Comment :	ground 2 camera sifting done in bracket and back side camera issue resoved																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	ground 2 camera sifting done in bracket and back side camera issue resoved																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-04-2025 05:10:32</td><td>Siddhesh Chavan</td><td>Completed</td><td>ground 2 camera sifting done in bracket and back side camera issue resoved</td><td></td></tr><tr><td>08-04-2025 05:00:35</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-04-2025 05:10:32	Siddhesh Chavan	Completed	ground 2 camera sifting done in bracket and back side camera issue resoved		08-04-2025 05:00:35	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																
08-04-2025 05:10:32	Siddhesh Chavan	Completed	ground 2 camera sifting done in bracket and back side camera issue resoved																	
08-04-2025 05:00:35	Siddhesh Chavan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>05-04-2025 05:15:03</td><td>Siddhesh Chavan</td><td>161 camera no 2 video issue resoved main gate and back gate fitting check ane update Levon Sir</td></tr><tr><td>31-03-2025 05:04:14</td><td>Siddhesh Chavan</td><td>Bus no 8 system check need to need to check battery Bangla outside camera issue, resolve, change, camera and old camera Take school Dvr 158 camera no 11 power and video check working ok under observation</td></tr></tbody></table>					Date Time	Technician Name	Remark	05-04-2025 05:15:03	Siddhesh Chavan	161 camera no 2 video issue resoved main gate and back gate fitting check ane update Levon Sir	31-03-2025 05:04:14	Siddhesh Chavan	Bus no 8 system check need to need to check battery Bangla outside camera issue, resolve, change, camera and old camera Take school Dvr 158 camera no 11 power and video check working ok under observation						
Date Time	Technician Name	Remark																		
05-04-2025 05:15:03	Siddhesh Chavan	161 camera no 2 video issue resoved main gate and back gate fitting check ane update Levon Sir																		
31-03-2025 05:04:14	Siddhesh Chavan	Bus no 8 system check need to need to check battery Bangla outside camera issue, resolve, change, camera and old camera Take school Dvr 158 camera no 11 power and video check working ok under observation																		