




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14825																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9930943918																			
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																
Ticket Type :	Complain	Date & Time :	27-05-2025 11:19:15																	
Vendor Details :																				
Company Name/Client Name :	St Joseph	Customer's Mobile :	9930943918	Name :	Levon															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	Some issue with the attendance device+ only 15 cameras on mobile So 1 camera is off																			
Technician Comment :	Biometric software install done and user data download done and ground side one camera angle setting done and one camera take to office because poe Port issue																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Biometric software install done and user data download done and ground side one camera angle setting done and one camera take to office because poe Port issue																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>27-05-2025 11:50:41</td><td>Siddhesh Chavan</td><td>Work Pending</td><td>Biometric software install done and user data download done and ground side one camera angle setting done and one camera take to office because poe Port issue</td><td></td></tr><tr><td>27-05-2025 11:19:21</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	27-05-2025 11:50:41	Siddhesh Chavan	Work Pending	Biometric software install done and user data download done and ground side one camera angle setting done and one camera take to office because poe Port issue		27-05-2025 11:19:21	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																
27-05-2025 11:50:41	Siddhesh Chavan	Work Pending	Biometric software install done and user data download done and ground side one camera angle setting done and one camera take to office because poe Port issue																	
27-05-2025 11:19:21	Siddhesh Chavan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>01-07-2025 11:23:55</td><td>Neeraj Chauhan</td><td>Power supply changed issue resolved and faulty collected</td></tr><tr><td>30-06-2025 05:27:09</td><td>Atique Salmani</td><td>Gate side one cameras reinstalled with changed 4*4 box and boath side vedeo baloon dc pin working ok.153 2nd 4 floor corridor 154 cameranmbr 6 7 floor corridor angel set Gate side one cameras reinstalled with changed 4*4 box and boath side vedeo baloon dc pin working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	01-07-2025 11:23:55	Neeraj Chauhan	Power supply changed issue resolved and faulty collected	30-06-2025 05:27:09	Atique Salmani	Gate side one cameras reinstalled with changed 4*4 box and boath side vedeo baloon dc pin working ok.153 2nd 4 floor corridor 154 cameranmbr 6 7 floor corridor angel set Gate side one cameras reinstalled with changed 4*4 box and boath side vedeo baloon dc pin working ok.						
Date Time	Technician Name	Remark																		
01-07-2025 11:23:55	Neeraj Chauhan	Power supply changed issue resolved and faulty collected																		
30-06-2025 05:27:09	Atique Salmani	Gate side one cameras reinstalled with changed 4*4 box and boath side vedeo baloon dc pin working ok.153 2nd 4 floor corridor 154 cameranmbr 6 7 floor corridor angel set Gate side one cameras reinstalled with changed 4*4 box and boath side vedeo baloon dc pin working ok.																		