## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Deta	ails : VE15327				
Priority:	Low				
Created By:	Admin - Apurva Vajaria				
Complaint Mob. No. :	9930943918				
Technician Name	Atique Salmani		Technician M	nician Mobile 8080922984	
Ticket Type :	Complain	Date & Time :	21-07-2025 04:04:25		
Vendor Details :			•		
Company Name/Client Name :	St Joseph	Customer's Mobile :	9930943918	Name:	Levon
Address:					
Mumbai , , , , Maha	arashtra				
AMC Details :					
Expiry Date :	31-03-2021 12:00:00		Type: Non-Comprehensive		ensive
<b>Product Name:</b>	CCTV				
Complain:	1)DVR 159 camera no. 10 disturbance issue 2)Bus no 6 One camera came out from socket by mistake as bus jumped				
Technician Comment :	159 camera 10 issue resolved and bus nmbr 6 camera fixed .				
Complain Operator :	Desktop - Apurva Vajaria				
Remark:	159 camera 10 issue resolved and bus nmbr 6 camera fixed .				
Status History :	Date Time	Technician Nai	me Status	Remark	Sign
	21-07-2025 04:28:27	7 Atique Salmani	Completed	159 camera 10 issue resolved and bus nmbr 6 camera fixed .	9 <del>70</del>
	21-07-2025 04:28:27	7 Atique Salmani	Completed	159 camera 10 issue resolved and bus nmbr 6 camera fixed .	970
	21-07-2025 04:04:30	Atique Salmani	New		-
Previous Complain	Date Time Technician Name		Remark		
History:	02-08-2025 12:56:26	Atique Salmani	0.57 is blurr need to changed can't remooved becz mach going on 0.54 offline collect for chek water insidee bullet camera And replacement camera installed main gate set angel . Working ok.		
		- i	In 151 nvr main gate camera 19 metr condute cabling done with new ip 66 box working ok.		