







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15467																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9930943918																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	02-08-2025 12:56:26																						
Vendor Details :																									
Company Name/Client Name :	St Joseph	Customer's Mobile :	9930943918	Name :	Levon																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																					
Product Name :	CCTV																								
Complain :	1)Turf some camera not clear Very Dull and some blur 2)School Turf camera no.16 replacement camera need to install against faulty																								
Technician Comment :	0.57 is blurr need to changed can't remooved becz mach going on 0.54 offline collect for chek water insidee bullet camera And replacement camera installed main gate set angel . Working ok.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	0.57 is blurr need to changed can't remooved becz mach going on 0.54 offline collect for chek water insidee bullet camera And replacement camera installed main gate set angel . Working ok.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>02-08-2025 03:23:28</td><td>Atique Salmani</td><td>Awaiting Spares</td><td>0.57 is blurr need to changed can't remooved becz mach going on 0.54 offline collect for chek water insidee bullet camera And replacement camera installed main gate set angel . Working ok.</td><td></td></tr><tr><td>02-08-2025 03:23:28</td><td>Atique Salmani</td><td>Awaiting Spares</td><td>0.57 is blurr need to changed can't remooved becz mach going on 0.54 offline collect for chek water insidee bullet camera And replacement camera installed main gate set angel . Working ok.</td><td></td></tr><tr><td>02-08-2025 12:56:33</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	02-08-2025 03:23:28	Atique Salmani	Awaiting Spares	0.57 is blurr need to changed can't remooved becz mach going on 0.54 offline collect for chek water insidee bullet camera And replacement camera installed main gate set angel . Working ok.		02-08-2025 03:23:28	Atique Salmani	Awaiting Spares	0.57 is blurr need to changed can't remooved becz mach going on 0.54 offline collect for chek water insidee bullet camera And replacement camera installed main gate set angel . Working ok.		02-08-2025 12:56:33	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
02-08-2025 03:23:28	Atique Salmani	Awaiting Spares	0.57 is blurr need to changed can't remooved becz mach going on 0.54 offline collect for chek water insidee bullet camera And replacement camera installed main gate set angel . Working ok.																						
02-08-2025 03:23:28	Atique Salmani	Awaiting Spares	0.57 is blurr need to changed can't remooved becz mach going on 0.54 offline collect for chek water insidee bullet camera And replacement camera installed main gate set angel . Working ok.																						
02-08-2025 12:56:33	Atique Salmani	New		-																					

Previous Complain History :	Date Time	Technician Name	Remark
	10-09-2025 05:12:37	Siddhesh Chavan	Turf Camera 16 = cabling change and camera issue resolved KG out Camera 5 = new camera install ans working ok Camera 13 = camera service centre mai hai NVR 167 Camera 4 = camera no link issue camera take to office for checking and cable need to check Camera 14 = no recoding view so pending DVR 165 IP camera 1 = need to change camera bullet camera NVR 151 Camera 9 = camera offline issue resolved and gate side new poe switch install and old take to office
	06-09-2025 11:19:19	ChandanYadav	NVR 151 camara no 9 camera working ok and required the 4 port switch. Cctv working ok