Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

| Service Status Details : VE15682 | | | | | | | | |
|----------------------------------|--|------------------------|------------------|----------------------|--------------|-------------------|------|--|
| Priority: | Low | | | | | | | |
| Created By: | Admin - Apurva Vajaria | | | | | | | |
| Complaint Mob. No. : | 9930943918 | | | | | | | |
| Technician Name : | Atique Salmani | | Technician Mobil | le 8080922984 | 8080922984 | | | |
| Ticket Type : | Complain Date & Time : | | ie: | 30-08-2025 05:03: | 55 | | | |
| Vendor Details : | lor Details : | | | | | | | |
| Company Name/Client Name : | St Joseph | Customer's Mobile : | | 9930943918 | Name : | Levon | | |
| Address: | ddress: | | | | | | | |
| Mumbai , , , , Maharashtra | | | | | | | | |
| AMC Details : | | | | | | | | |
| Expiry Date : | 31-03-2021 12:00:00 | | | Type: | Non-Comprehe | Non-Comprehensive | | |
| Product Name: | CCTV | | | | | | | |
| Complain: | School and turf many cameras issue need to check | | | | | | | |
| Technician Comment : | | | | | | | | |
| Complain Operator : | Desktop - Apurva Vajaria | | | | | | | |
| Remark : | NVR 151 Camera 9: Cable to be put via route told by Mr David on Tuesday 26th Aug done by 53 metr cabling done ???? DVR 153 Camera 3: Alignment / shifting to be done due to a cupboard being placed in the corridor done ???? by shift DVR 163 Cameras 7 and 8: Disturbance done ???? DVR 165 IP Camera 1: Taken out service center NVR 167 IP Camera 4: Not working done ???? KG OUT Camera 3: Facing Wrong Direction Alignment was shifted by team who visited on 20th August around 12.50pm done ???? Camera 5: Not working / Taken out service center Turf IP Camera 8: Blurry and alignment needed done ???? IP Camera 9: Camera image foggy also alignment needed done ???? IP Camera 15: Facing Wrong Direction Alignment was shifted by team who visited turf on 20th August around 6.30pm done ???? | | | | | | | |
| Status History : | Date Tir | ne | Te | echnician Name | Status | Remark | Sign | |
| | 11-09-2025 01:30:4 | 12 | Atique | Salmani | Completed | | - | |
| | 30-08-2025 05:04:0 |)1 | Atique | Salmani | New | | - | |

| Previous Complain History : | Date Time | Technician Name | Remark | | |
|-----------------------------------|------------------------|-----------------|---|--|--|
| | 10-09-2025 05:12:37 | Siddhesh Chavan | Turf Camera 16 = cabling change and camera issue resolved KG out Camera 5 = new camera install ans working ok Camera 13 = camera service centre mai hai NVR 167 Camera 4 = camera no link issue camera take to office for checking and cable need to check Camera 14 = no recoding view so pending DVR 165 IP camera 1 = need to change camera bullet camera NVR 151 Camera 9 = camera offline issue resolved and gate side new poe switch install and old take to office | | |
| | 06-09-2025 11:19:19 | ChandanYadav | NVR 151 camara no 9 camera working ok and required the 4 port switch. Cctv working ok | | |