







# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE16115</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9930943918																								
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	30-10-2025 11:30:23																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	St Joseph	Customer's Mobile :	9930943918	Name :	Levon																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																					
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	1)DVR_159 IP Camera PTZ 2)Turf IP Camera 13 3)Bus no 8 dvr view issue pending 4)1 camera view pending																								
<b>Technician Comment :</b>	Ptz issue resolved 151 16 cameras working turf 13 nmbr camera ipc connector rushted so collect camera and also cable is too short need new cabling with ip 66 box .																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	Ptz issue resolved 151 16 cameras working turf 13 nmbr camera ipc connector rushted so collect camera and also cable is too short need new cabling with ip 66 box .																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>30-10-2025 02:31:02</td><td>Atique Salmani</td><td>Awaiting Spares</td><td>Ptz issue resolved 151 16 cameras working turf 13 nmbr camera ipc connector rushted so collect camera and also cable is too short need new cabling with ip 66 box .</td><td></td></tr><tr><td>30-10-2025 02:31:02</td><td>Atique Salmani</td><td>Awaiting Spares</td><td>Ptz issue resolved 151 16 cameras working turf 13 nmbr camera ipc connector rushted so collect camera and also cable is too short need new cabling with ip 66 box .</td><td></td></tr><tr><td>30-10-2025 11:30:31</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	30-10-2025 02:31:02	Atique Salmani	Awaiting Spares	Ptz issue resolved 151 16 cameras working turf 13 nmbr camera ipc connector rushted so collect camera and also cable is too short need new cabling with ip 66 box .		30-10-2025 02:31:02	Atique Salmani	Awaiting Spares	Ptz issue resolved 151 16 cameras working turf 13 nmbr camera ipc connector rushted so collect camera and also cable is too short need new cabling with ip 66 box .		30-10-2025 11:30:31	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
30-10-2025 02:31:02	Atique Salmani	Awaiting Spares	Ptz issue resolved 151 16 cameras working turf 13 nmbr camera ipc connector rushted so collect camera and also cable is too short need new cabling with ip 66 box .																						
30-10-2025 02:31:02	Atique Salmani	Awaiting Spares	Ptz issue resolved 151 16 cameras working turf 13 nmbr camera ipc connector rushted so collect camera and also cable is too short need new cabling with ip 66 box .																						
30-10-2025 11:30:31	Atique Salmani	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>12-12-2025 10:01:58</td><td>Atique Salmani</td><td>1st floor beep sound becZ 16 nmbr camera was off now issue resolved working ok and 3rd floor allready no beep sound</td></tr><tr><td>09-12-2025 04:17:30</td><td>Neeraj Chauhan</td><td>DVR 159 New 4 TB HDD install done Bus no 1 CMOS battery change</td></tr></tbody></table>					Date Time	Technician Name	Remark	12-12-2025 10:01:58	Atique Salmani	1st floor beep sound becZ 16 nmbr camera was off now issue resolved working ok and 3rd floor allready no beep sound	09-12-2025 04:17:30	Neeraj Chauhan	DVR 159 New 4 TB HDD install done Bus no 1 CMOS battery change											
Date Time	Technician Name	Remark																							
12-12-2025 10:01:58	Atique Salmani	1st floor beep sound becZ 16 nmbr camera was off now issue resolved working ok and 3rd floor allready no beep sound																							
09-12-2025 04:17:30	Neeraj Chauhan	DVR 159 New 4 TB HDD install done Bus no 1 CMOS battery change																							