

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
 Support : | W : www.vallabhenterprises.com
 E : vallabhsecure@yahoo.co.in

Service Status Details : VE2143																				
Priority :	High																			
Created By :	Customer - Madhu Sir- Mt																			
Complaint Mob. No. :	9742015015																			
Technician Name :		Technician Mobile :																		
Ticket Type :	Complain	Date & Time :	31-10-2020 06:33:24																	
Vendor Details :																				
Company Name/Client Name :	Concentrix Services India Private Limited - MT	Customer's Mobile :	9742015015	Name :	Madhu Sir-Mt															
Address :																				
Bangalore , , , 560037 , Karnataka																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00	Type :																		
Product Name :	CCTV																			
Complain :	Fire exit door panic Bar bazaar is not working at 2nd floor																			
Technician Comment :																				
Complain Operator :	Desktop - Madhu Sir- Mt																			
Remark :	we have replaced 12 v supply for emergency exit now exit buzzer working normal																			
Status History :	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Status</th> <th>Remark</th> <th>Sign</th> </tr> </thead> <tbody> <tr> <td>02-11-2020 11:20:27</td> <td></td> <td>Completed</td> <td></td> <td>-</td> </tr> <tr> <td>31-10-2020 06:33:25</td> <td></td> <td>New</td> <td></td> <td>-</td> </tr> </tbody> </table>					Date Time	Technician Name	Status	Remark	Sign	02-11-2020 11:20:27		Completed		-	31-10-2020 06:33:25		New		-
Date Time	Technician Name	Status	Remark	Sign																
02-11-2020 11:20:27		Completed		-																
31-10-2020 06:33:25		New		-																
Previous Complain History :	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Remark</th> </tr> </thead> <tbody> <tr> <td>14-11-2020 08:37:53</td> <td></td> <td>All access door problem solved. Now all doors working properly Buzzer working properly</td> </tr> <tr> <td>10-11-2020 02:50:42</td> <td></td> <td>We checked the came BNC connector problem now that camera is working</td> </tr> </tbody> </table>					Date Time	Technician Name	Remark	14-11-2020 08:37:53		All access door problem solved. Now all doors working properly Buzzer working properly	10-11-2020 02:50:42		We checked the came BNC connector problem now that camera is working						
Date Time	Technician Name	Remark																		
14-11-2020 08:37:53		All access door problem solved. Now all doors working properly Buzzer working properly																		
10-11-2020 02:50:42		We checked the came BNC connector problem now that camera is working																		