

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6642																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	7738060558																								
Technician Name :	Munna Gupta		Technician Mobile :	8080922982																					
Ticket Type :	Complain	Date & Time :	20-10-2022 10:49:27																						
Vendor Details :																									
Company Name/Client Name :	Vinayak Developers	Customer's Mobile :	7738060558	Name :	Malesh Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	4 cameras off issue																								
Technician Comment :	ptz camera shifting and preset setting. ptz camere ka glass damage ho chuka hai jiski wajah se picture clear nahin a raha hai.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	ptz camera shifting and preset setting. ptz camere ka glass damage ho chuka hai jiski wajah se picture clear nahin a raha hai.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>02-11-2022 07:15:06</td><td>Munna Gupta</td><td>Completed</td><td>ptz camera shifting and preset setting. ptz camere ka glass damage ho chuka hai jiski wajah se picture clear nahin a raha hai.</td><td></td></tr><tr><td>02-11-2022 07:07:22</td><td>Munna Gupta</td><td>New</td><td></td><td>-</td></tr><tr><td>20-10-2022 03:24:28</td><td>Munna Gupta</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	02-11-2022 07:15:06	Munna Gupta	Completed	ptz camera shifting and preset setting. ptz camere ka glass damage ho chuka hai jiski wajah se picture clear nahin a raha hai.		02-11-2022 07:07:22	Munna Gupta	New		-	20-10-2022 03:24:28	Munna Gupta	New		-
Date Time	Technician Name	Status	Remark	Sign																					
02-11-2022 07:15:06	Munna Gupta	Completed	ptz camera shifting and preset setting. ptz camere ka glass damage ho chuka hai jiski wajah se picture clear nahin a raha hai.																						
02-11-2022 07:07:22	Munna Gupta	New		-																					
20-10-2022 03:24:28	Munna Gupta	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>30-03-2021 10:01:43</td><td>Ravi Rajbhar</td><td>2 camera started and angle setting has been done 1 camera of back gate has cable issue (no continuity) ptz camera controll from hik connect enabled.</td></tr><tr><td>22-03-2021 09:56:35</td><td>RishiDesai</td><td>One Ptz camera auto mode preset done. 2 cameras Not working , One Camera Needed Bnc pin to change because of rcc, One camera no connection ot bnc and dc and one camera angle setting.</td></tr></tbody></table>					Date Time	Technician Name	Remark	30-03-2021 10:01:43	Ravi Rajbhar	2 camera started and angle setting has been done 1 camera of back gate has cable issue (no continuity) ptz camera controll from hik connect enabled.	22-03-2021 09:56:35	RishiDesai	One Ptz camera auto mode preset done. 2 cameras Not working , One Camera Needed Bnc pin to change because of rcc, One camera no connection ot bnc and dc and one camera angle setting.											
Date Time	Technician Name	Remark																							
30-03-2021 10:01:43	Ravi Rajbhar	2 camera started and angle setting has been done 1 camera of back gate has cable issue (no continuity) ptz camera controll from hik connect enabled.																							
22-03-2021 09:56:35	RishiDesai	One Ptz camera auto mode preset done. 2 cameras Not working , One Camera Needed Bnc pin to change because of rcc, One camera no connection ot bnc and dc and one camera angle setting.																							