Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE1651									
Priority:	High								
Created By:	Admin - Apurva Vajaria								
Complaint Mob. No. :	9833125148								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984					
Ticket Type:	Complain	Date & Time:	06-08-2020 05:15:40						
Vendor Details :									
Company Name/Client Name:	Mandar Pushpa	Customer's Mobile :	9833125148	Name :	Mandar Pushpa Vijay				
Address:									
Mumbai , , , , Maharashtra									
AMC Details :									
Expiry Date :	31-07-2020 12:00:00		Type:	Comprehensive					
Product Name:	VDP								
Complain:	103 , 501 phone Ringing Continuously								
Technician Comment :	103 vdp installed and working ok. 501 paniding camera issue continue ringing so colect camera for check and test. also receeved 2 check one painding. aftr 501 cometed will give next check.								
Complain Operator :	Desktop - Apurva Vajaria								
Remark:	103 vdp installed and working ok. 501 paniding camera issue continue ringing so colect camera for check and test. also receeved 2 check one painding. aftr 501 cometed will give next check.								

Status History :	Date Time	Technician Name	9	Status	Remark	Sign
	08-08-2020 06:10:15	Atique Salmani	Com	pleted	103 vdp installed and working ok. 501 paniding camera issue continue ringing so colect camera for check and test. also receceved 2 check one painding. aftr 501 cometed will give next check.	Kru
	07-08-2020 06:13:00	Atique Salmani	New			-
	07-08-2020 06:12:57	Atique Salmani	New			-
	06-08-2020 05:25:02	Atique Salmani	Wor	k Pending		-
	06-08-2020 05:23:38	Atique Salmani	Completed		We have checked the Video Door Phone of Flat no 103, 301 and 501 (Anand Sir). Flat no 301 was working perfectly in front of us. Flat no 103 and 501 was checked too also checked duct and video distributor with RJ45 Lan Tester. As per Vijay sir informed Atiq about that take video door phone of (Anand Sir) 501 and 103 to take the Vdp screen to office for testing.	RAN
	06-08-2020 05:15:49	Atique Salmani	New			-
	06-08-2020 05:15:41	Atique Salmani	New			-
Previous Complain History :	Date Time			Technician Name		Remark
	30-07-2020 11:03:47			Siddhesh Chavan		
	02-07-2020 11:30:34			Atique Salmani		