

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2391																																								
Priority :	High																																							
Created By :	Admin - Apurva Vajaria																																							
Complaint Mob. No. :	9819810798																																							
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																																				
Ticket Type :	Complain	Date & Time :	08-12-2020 03:56:11																																					
Vendor Details :																																								
Company Name/Client Name :	Louis Palace Co Op Hsg Soc. Ltd	Customer's Mobile :	9819810798	Name :	Manoj Sir																																			
Address :																																								
Mumbai , , , , Maharashtra																																								
AMC Details :																																								
Expiry Date :	30-06-2021 12:00:00		Type :	Non-Comprehensive																																				
Product Name :	Intercom																																							
Complain :	ppm to be done																																							
Technician Comment :	intercom all flat ppm done a wing b wing and office line ok instrument issue																																							
Complain Operator :	Desktop - Apurva Vajaria																																							
Remark :	intercom all flat ppm done a wing b wing and office line ok instrument issue																																							
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-12-2020 02:15:00</td><td>Ravi Rajbhar</td><td>Completed</td><td>intercom all flat ppm done a wing b wing and office line ok instrument issue</td><td></td></tr><tr><td>10-12-2020 10:48:18</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>09-12-2020 06:20:16</td><td>Ravi Rajbhar</td><td>Work Pending</td><td></td><td>-</td></tr><tr><td>09-12-2020 10:14:15</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>08-12-2020 03:56:27</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>08-12-2020 03:56:11</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-12-2020 02:15:00	Ravi Rajbhar	Completed	intercom all flat ppm done a wing b wing and office line ok instrument issue		10-12-2020 10:48:18	Ravi Rajbhar	New		-	09-12-2020 06:20:16	Ravi Rajbhar	Work Pending		-	09-12-2020 10:14:15	Ravi Rajbhar	New		-	08-12-2020 03:56:27	Ravi Rajbhar	New		-	08-12-2020 03:56:11	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																																				
10-12-2020 02:15:00	Ravi Rajbhar	Completed	intercom all flat ppm done a wing b wing and office line ok instrument issue																																					
10-12-2020 10:48:18	Ravi Rajbhar	New		-																																				
09-12-2020 06:20:16	Ravi Rajbhar	Work Pending		-																																				
09-12-2020 10:14:15	Ravi Rajbhar	New		-																																				
08-12-2020 03:56:27	Ravi Rajbhar	New		-																																				
08-12-2020 03:56:11	Ravi Rajbhar	New		-																																				
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-11-2020 04:09:54</td><td>Ravi Rajbhar</td><td>epbax system co line connect with canfiguration done and online done</td></tr><tr><td>23-09-2020 11:22:53</td><td>AnilYadav</td><td>Not available complaint list. Security cabin line not working because cable is faulty. Display cable to connect then working but display is not working now.</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-11-2020 04:09:54	Ravi Rajbhar	epbax system co line connect with canfiguration done and online done	23-09-2020 11:22:53	AnilYadav	Not available complaint list. Security cabin line not working because cable is faulty. Display cable to connect then working but display is not working now.																										
Date Time	Technician Name	Remark																																						
19-11-2020 04:09:54	Ravi Rajbhar	epbax system co line connect with canfiguration done and online done																																						
23-09-2020 11:22:53	AnilYadav	Not available complaint list. Security cabin line not working because cable is faulty. Display cable to connect then working but display is not working now.																																						