




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support :** | **W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE5173</b>					
<b>Priority :</b>	Low				
<b>Created By :</b>	Admin - Apurva Vajaria				
<b>Complaint Mob. No. :</b>	9820574739				
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965	
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	11-04-2022 11:29:04		
<b>Vendor Details :</b>					
Company Name/Client Name :	Keshav Industrial Estate	Customer's Mobile :	9820574739	Name :	Manoj Sir
<b>Address :</b>					
Mumbai , , , , Maharashtra					
<b>AMC Details :</b>					
Expiry Date :	01-01-1970 05:30:00		Type :		
<b>Product Name :</b>	Access				
<b>Complain :</b>	door lock access issue				
<b>Technician Comment :</b>	main door lock install and ok working done and faulty lock return to client				
<b>Complain Operator :</b>	Desktop - Apurva Vajaria				
<b>Remark :</b>	main door lock install and ok working done and faulty lock return to client				

Status History :

Date Time	Technician Name	Status	Remark	Sign
16-04-2022 01:15:21	Ravi Rajbhar	Completed	main door lock install and ok working done and faulty lock return to client	
16-04-2022 10:59:28	Ravi Rajbhar	New		-
15-04-2022 11:32:49	Ravi Rajbhar	New		-
14-04-2022 01:17:11	Ravi Rajbhar	New		-
14-04-2022 10:20:42	Ravi Rajbhar	New		-
13-04-2022 07:59:57	Ravi Rajbhar	Work Pending	door issue not sloved work pending.	
13-04-2022 06:51:02	Ravi Rajbhar	New		-
11-04-2022 01:05:13	Ravi Rajbhar	Work Pending	door lock side one Yale dives out dc voltage issue	
11-04-2022 01:01:52	Ravi Rajbhar	New		-
11-04-2022 11:29:21	Ravi Rajbhar	New		-
11-04-2022 11:29:04	Ravi Rajbhar	New		-

Previous Complain History :

Date Time	Technician Name	Remark
01-02-2022 10:12:18	Atique Salmani	check hdd status and it's normal it was not working due to heating being on off system was too heat so I suggest to on a/c now it's working keep on under observation.
22-12-2021 10:07:38	Atique Salmani	changed 3 BNC connector camera nmbr nmbr 13 14/16 all working ok.