




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7000																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9819810798																			
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																
Ticket Type :	Complain	Date & Time :	02-12-2022 03:48:42																	
Vendor Details :																				
Company Name/Client Name :	Louis Palace Co Op Hsg Soc. Ltd	Customer's Mobile :	9819810798	Name :	Manoj Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	30-06-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	Intercom																			
Complain :	b 401 flat intercom issue																			
Technician Comment :	b wing 401 intercom issue resolved flat out side repunch cable and line working ok																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	b wing 401 intercom issue resolved flat out side repunch cable and line working ok																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>02-12-2022 04:07:18</td><td>Siddhesh Chavan</td><td>Completed</td><td>b wing 401 intercom issue resolved flat out side repunch cable and line working ok</td><td></td></tr><tr><td>02-12-2022 03:48:51</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	02-12-2022 04:07:18	Siddhesh Chavan	Completed	b wing 401 intercom issue resolved flat out side repunch cable and line working ok		02-12-2022 03:48:51	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																
02-12-2022 04:07:18	Siddhesh Chavan	Completed	b wing 401 intercom issue resolved flat out side repunch cable and line working ok																	
02-12-2022 03:48:51	Siddhesh Chavan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>24-11-2022 06:28:52</td><td>Ravi Rajbhar</td><td>a wing 104,203,204,303,304 cable checking pending flat to duct b wing check all flat intercom</td></tr><tr><td>14-11-2022 11:05:58</td><td>Shiva Meena</td><td>ppm done</td></tr></tbody></table>					Date Time	Technician Name	Remark	24-11-2022 06:28:52	Ravi Rajbhar	a wing 104,203,204,303,304 cable checking pending flat to duct b wing check all flat intercom	14-11-2022 11:05:58	Shiva Meena	ppm done						
Date Time	Technician Name	Remark																		
24-11-2022 06:28:52	Ravi Rajbhar	a wing 104,203,204,303,304 cable checking pending flat to duct b wing check all flat intercom																		
14-11-2022 11:05:58	Shiva Meena	ppm done																		