

# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE6255</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9869695781																													
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																										
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	27-08-2022 09:59:03																											
<b>Vendor Details :</b>																														
<b>Company Name/Client Name :</b>	Kuber Co Op Society	<b>Customer's Mobile :</b>	9869695781	<b>Name :</b>	Mansukh Sir																									
<b>Address :</b>																														
Mumbai , , , 400067 , Maharashtra																														
<b>AMC Details :</b>																														
<b>Expiry Date :</b>	31-03-2021 12:00:00		<b>Type :</b>	Non-Comprehensive																										
<b>Product Name :</b>	CCTV																													
<b>Complain :</b>	A wing 6th floor 1 camera flickering issue																													
<b>Technician Comment :</b>	a wing camera nmbr 6 ground floor flickring issue need to changed camera . also same issue b wing terrace camera also need to changed .																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	a wing camera nmbr 6 ground floor flickring issue need to changed camera . also same issue b wing terrace camera also need to changed .																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>27-08-2022 11:23:29</td><td>Atique Salmani</td><td>Completed</td><td>a wing camera nmbr 6 ground floor flickring issue need to changed camera . also same issue b wing terrace camera also need to changed .</td><td></td></tr><tr><td>27-08-2022 10:03:39</td><td>Atique Salmani</td><td>Work Pending</td><td>a wing camera nmbr 6 ground floor flickring issue need to changed camera . also same issue b wing terrace camera also need to changed .</td><td></td></tr><tr><td>27-08-2022 09:59:14</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>27-08-2022 09:59:03</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	27-08-2022 11:23:29	Atique Salmani	Completed	a wing camera nmbr 6 ground floor flickring issue need to changed camera . also same issue b wing terrace camera also need to changed .		27-08-2022 10:03:39	Atique Salmani	Work Pending	a wing camera nmbr 6 ground floor flickring issue need to changed camera . also same issue b wing terrace camera also need to changed .		27-08-2022 09:59:14	Atique Salmani	New		-	27-08-2022 09:59:03	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
27-08-2022 11:23:29	Atique Salmani	Completed	a wing camera nmbr 6 ground floor flickring issue need to changed camera . also same issue b wing terrace camera also need to changed .																											
27-08-2022 10:03:39	Atique Salmani	Work Pending	a wing camera nmbr 6 ground floor flickring issue need to changed camera . also same issue b wing terrace camera also need to changed .																											
27-08-2022 09:59:14	Atique Salmani	New		-																										
27-08-2022 09:59:03	Atique Salmani	New		-																										

Previous Complain History :			
	Date Time	Technician Name	Remark
	29-08-2022 11:48:06	Sonu Kumar	recording seen completed
	25-08-2022 05:07:54	Shiva Meena	recoding calint mobile done