

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE10434																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9833222801																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	02-01-2024 05:06:25																	
Vendor Details :																				
Company Name/Client Name :	Poonam Cluster	Customer's Mobile :	9833222801	Name :	Mateen Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Access																			
Complain :	B2 lobby biometric off issue (No power issue)																			
Technician Comment :	B2 lobby access SMPS faulty so changed new sf SMPS and working ok.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	B2 lobby access SMPS faulty so changed new sf SMPS and working ok.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>03-01-2024 05:35:56</td><td>Atique Salmani</td><td>Completed</td><td>B2 lobby access SMPS faulty so changed new sf SMPS and working ok.</td><td></td></tr><tr><td>02-01-2024 05:29:52</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	03-01-2024 05:35:56	Atique Salmani	Completed	B2 lobby access SMPS faulty so changed new sf SMPS and working ok.		02-01-2024 05:29:52	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
03-01-2024 05:35:56	Atique Salmani	Completed	B2 lobby access SMPS faulty so changed new sf SMPS and working ok.																	
02-01-2024 05:29:52	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>20-12-2023 05:26:08</td><td>Atique Salmani</td><td>B1 power supply faulty so changed new self 12 volt 5 Amps SMPS now working ok.</td></tr><tr><td>11-12-2023 12:20:50</td><td>Siddhesh Chavan</td><td>b=1 exit button issue resolved and b=3 door lock working OK door alignment issue</td></tr></tbody></table>					Date Time	Technician Name	Remark	20-12-2023 05:26:08	Atique Salmani	B1 power supply faulty so changed new self 12 volt 5 Amps SMPS now working ok.	11-12-2023 12:20:50	Siddhesh Chavan	b=1 exit button issue resolved and b=3 door lock working OK door alignment issue						
Date Time	Technician Name	Remark																		
20-12-2023 05:26:08	Atique Salmani	B1 power supply faulty so changed new self 12 volt 5 Amps SMPS now working ok.																		
11-12-2023 12:20:50	Siddhesh Chavan	b=1 exit button issue resolved and b=3 door lock working OK door alignment issue																		