




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE10736																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9870150010																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	02-02-2024 02:17:05																	
Vendor Details :																				
Company Name/Client Name :	Mehul Mehta (CA)	Customer's Mobile :	9870150010	Name :	Mehul Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	DVR beep sound issue																			
Technician Comment :	In side office camera was off so chek and changed BNC connector from camera end working ok but on under observation.if again off then ca era need to changed .																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	In side office camera was off so chek and changed BNC connector from camera end working ok but on under observation.if again off then ca era need to changed .																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>03-02-2024 11:24:32</td><td>Atique Salmani</td><td>Completed</td><td>In side office camera was off so chek and changed BNC connector from camera end working ok but on under observation.if again off then ca era need to changed .</td><td></td></tr><tr><td>03-02-2024 10:27:10</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	03-02-2024 11:24:32	Atique Salmani	Completed	In side office camera was off so chek and changed BNC connector from camera end working ok but on under observation.if again off then ca era need to changed .		03-02-2024 10:27:10	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
03-02-2024 11:24:32	Atique Salmani	Completed	In side office camera was off so chek and changed BNC connector from camera end working ok but on under observation.if again off then ca era need to changed .																	
03-02-2024 10:27:10	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>20-12-2023 06:27:39</td><td></td><td></td></tr><tr><td>20-12-2023 03:39:05</td><td>MayurYadav</td><td>Recording show And one camera offline issue solve</td></tr></tbody></table>					Date Time	Technician Name	Remark	20-12-2023 06:27:39			20-12-2023 03:39:05	MayurYadav	Recording show And one camera offline issue solve						
Date Time	Technician Name	Remark																		
20-12-2023 06:27:39																				
20-12-2023 03:39:05	MayurYadav	Recording show And one camera offline issue solve																		