




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE554																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9930908642																								
Technician Name :	Zainul Shaikh		Technician Mobile :	8080922971																					
Ticket Type :	Complain	Date & Time :	18-10-2019 11:57:14																						
Vendor Details :																									
Company Name/Client Name :	Flemingo Duty Free Shop Pvt Ltd	Customer's Mobile :	9930908642	Name :	Methue																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	30-07-2021 12:00:00		Type :	Non-Comprehensive																					
Product Name :	CCTV																								
Complain :	cctv survey																								
Technician Comment :	6 power supply faulty need to change. and required 50 meter cable to install 2 new camera																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	6 power supply faulty need to change. and required 50 meter cable to install 2 new camera																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-10-2019 10:05:08</td><td>ZainulShaikh</td><td>Completed</td><td>6 power supply faulty need to change. and required 50 meter cable to install 2 new camera</td><td></td></tr><tr><td>22-10-2019 06:35:38</td><td>ZainulShaikh</td><td>New</td><td></td><td>-</td></tr><tr><td>18-10-2019 11:57:15</td><td>ZainulShaikh</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-10-2019 10:05:08	ZainulShaikh	Completed	6 power supply faulty need to change. and required 50 meter cable to install 2 new camera		22-10-2019 06:35:38	ZainulShaikh	New		-	18-10-2019 11:57:15	ZainulShaikh	New		-
Date Time	Technician Name	Status	Remark	Sign																					
24-10-2019 10:05:08	ZainulShaikh	Completed	6 power supply faulty need to change. and required 50 meter cable to install 2 new camera																						
22-10-2019 06:35:38	ZainulShaikh	New		-																					
18-10-2019 11:57:15	ZainulShaikh	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>04-02-2022 10:30:03</td><td>Siddhesh Chavan</td><td>ppm done and dack side gate camera rj6 cable issue and camera working ok and camera take to dvr room and 1 st no camera recording just started</td></tr><tr><td>30-08-2021 11:44:08</td><td>Neeraj Chauhan</td><td>all camera cleaning and housing cleaning and dvr time date set and and dvr function check and 1 camera no video issue solve and 1 camera not working and 16 channel dvr not working and ppm done</td></tr></tbody></table>					Date Time	Technician Name	Remark	04-02-2022 10:30:03	Siddhesh Chavan	ppm done and dack side gate camera rj6 cable issue and camera working ok and camera take to dvr room and 1 st no camera recording just started	30-08-2021 11:44:08	Neeraj Chauhan	all camera cleaning and housing cleaning and dvr time date set and and dvr function check and 1 camera no video issue solve and 1 camera not working and 16 channel dvr not working and ppm done											
Date Time	Technician Name	Remark																							
04-02-2022 10:30:03	Siddhesh Chavan	ppm done and dack side gate camera rj6 cable issue and camera working ok and camera take to dvr room and 1 st no camera recording just started																							
30-08-2021 11:44:08	Neeraj Chauhan	all camera cleaning and housing cleaning and dvr time date set and and dvr function check and 1 camera no video issue solve and 1 camera not working and 16 channel dvr not working and ppm done																							